SIEMENS

SIMOVERT MASTERDRIVES Motion Control

Betriebsanleitung Operating Instructions

Wechselrichter (DC-AC) Bauform Kompakt Inverter (DC-AC) Compact Type

Ausgabe / Edition: AD

Bestell-Nr. / Order No.: 6SE7087-6KD50

Diese Betriebsanleitung gilt für den Gerätesoftwarestand V 1.4.

Änderungen von Funktionen, technischen Daten, Normen, Zeichnungen und Parametern vorbehalten.

These Operating Instructions are valid for software release V 1.4.

We reserve the right to make changes to functions, technical data, standards, drawings and parameters.

Weitergabe sowie Vervielfältigung dieser Unterlage, Verwertung und Mitteilung ihres Inhalts nicht gestattet, soweit nicht ausdrücklich zugestanden. Zuwiderhandlungen verpflichten zu Schadenersatz. Alle Rechte vorbehalten, insbesondere für den Fall der Patenterteilung oder GM-Eintragung,

Wir haben den Inhalt der Druckschrift auf Übereinstimmung mit der beschriebenen Hard- und Software überprüft. Dennoch können Abweichungen nicht ausgeschlossen werden, so daß wir für die vollständige Übereinstimmung keine Garantie übernehmen. Die Angaben in dieser Druckschrift werden jedoch regelmäßig überprüft und notwendige Korrekturen sind in den nachfolgenden Auflagen enthalten. Für Verbesserungsvorschläge sind wir dankbar

The reproduction, transmission or use of this document or its contents is not permitted without express written authority. Offenders will be liable for damages. All rights, including rights created by patent grant or registration of a utility model or design, are reserved.

We have checked the contents of this document to ensure that they coincide with the described hardware and software. However, differences cannot be completely excluded, so that we do not accept any guarantee for complete conformance. However, the information in this document is regularly checked and necessary corrections will be included in subsequent editions. We are grateful for any recommendations for improvement.

SIMOVERT® ist ein Warenzeichen von Siemens

SIMOVERT® Registered Trade Mark

Contents

1	DEFINITIONS AND WARNINGS	1-1
2	DESCRIPTION	2-1
3	FIRST START-UP	3-1
4	TRANSPORT, STORAGE, UNPACKING	4-1
5	INSTALLATION	5-1
5.1	Installing the unit	5-1
5.2	Installing the optional boards	5-4
6	INSTALLATION IN CONFORMANCE WITH EMC REGULATIONS	6-1
7	CONNECTING-UP	
7.1	Power connections	7-4
7.2	Control connections	7-7
7.3	Fan fuses	7-11
8	PARAMETERIZATION	8-1
8.1	Parameter input via the PMU	8-2
8.2	Parameter input via the OP1S	8-5
8.3	Parameter reset to factory setting	8-9
8.4	Parameterizing by download	8-10
8.5	Parameterizing with parameter modules	8-11
8.6	Motor lists	8-25
8.7	Motor identification	8-30
8.8	Complete parameterization	8-30

9	MAINTENANCE	9-1
9.1	Replacing the fan	9-2
9.2	Replacing the PMU	9-4
9.3	Replacing the DC link fuses	9-5
10	FORMING	
11	TECHNICAL DATA	11-1
12	FAULTS AND ALARMS	12-1
12.1	Faults	12-1
12.2	Alarms	12-13
12.3	Fatal errors (FF)	12-35
13	ENVIRONMENTAL FRIENDLINESS	13-1
14	CERTIFICATES	14-1

1 Definitions and Warnings

Qualified personnel

For the purpose of this documentation and the product warning labels, a "Qualified person" is someone who is familiar with the installation, mounting, start-up, operation and maintenance of the product. He or she must have the following qualifications:

- Trained or authorized to energize, de-energize, ground and tag circuits and equipment in accordance with established safety procedures.
- ◆ Trained or authorized in the proper care and use of protective equipment in accordance with established safety procedures.
- Trained in rendering first aid.

DANGER



For the purpose of this documentation and the product warning labels, "Danger" indicates death, severe personal injury or substantial property damage will result if proper precautions are not taken.

WARNING



For the purpose of this documentation and the product warning labels, "Warning" indicates death, severe personal injury or property damage can result if proper precautions are not taken.

CAUTION



For the purpose of this documentation and the product warning labels, "Caution" indicates that minor personal injury or material damage can result if proper precautions are not taken.

NOTE

For the purpose of this documentation, "Note" indicates important information about the product or about the respective part of the documentation which is essential to highlight.

Definitions and Warnings 10.98

WARNING



Hazardous voltages are present in this electrical equipment during operation.

Non-observance of the warnings can thus result in severe personal injury or property damage.

Only qualified personnel should work on or around the equipment

This personnel must be thoroughly familiar with all warning and maintenance procedures contained in this documentation.

The successful and safe operation of this equipment is dependent on correct transport, proper storage and installation as well as careful operation and maintenance.

NOTE

This documentation does not purport to cover all details on all types of the product, nor to provide for every possible contingency to be met in connection with installation, operation or maintenance.

Should further information be desired or should particular problems arise which are not covered sufficiently for the purchaser's purposes, the matter should be referred to the local SIEMENS sales office.

The contents of this documentation shall not become part of or modify any prior or existing agreement, commitment or relationship. The sales contract contains the entire obligation of SIEMENS AG. The warranty contained in the contract between the parties is the sole warranty of SIEMENS AG. Any statements contained herein do not create new warranties or modify the existing warranty.

CAUTION



Components which can be destroyed by electrostatic discharge (ESD)

The board contains components which can be destroyed by electrostatic discharge. These components can be easily destroyed if not carefully handled. If you have to handle electronic boards, please observe the following:

Electronic boards should only be touched when absolutely necessary.

The human body must be electrically discharged before touching an electronic board.

Boards must not come into contact with highly insulating materials - e.g. plastic parts, insulated desktops, articles of clothing manufactured from man-made fibers.


Boards must only be placed on conductive surfaces.


Boards and components should only be stored and transported in conductive packaging (e.g. metalized plastic boxes or metal containers).

If the packing material is not conductive, the boards must be wrapped with a conductive packaging material, e.g. conductive foam rubber or household aluminium foil.

The necessary ESD protective measures are clearly shown again in the following diagram:

- ♦ a = Conductive floor surface
- ♦ b = ESD table
- ♦ c = ESD shoes
- ♦ d = ESD overall
- ♦ e = ESD chain
- ♦ f = Cubicle ground connection








Fig. 1-1

ESD protective measures

Definitions and Warnings 10.98



Safety and Operating Instructions for Drive Converters

(in conformity with the low-voltage directive 73/23/EEC)

1. General

In operation, drive converters, depending on their degree of protection, may have live, uninsulated, and possibly also moving or rotating parts, as well as hot surfaces.

In case of inadmissible removal of the required covers, of improper use, wrong installation or maloperation, there is the danger of serious personal injury and damage to property.

For further information, see documentation.

All operations serving transport, installation and commissioning as well as maintenance are to be carried out **by skilled technical personnel** (observe IEC 364 or CENELEC HD 384 or DIN VDE 0100 and IEC Report 664 or DIN VDE 0110 and national accident prevention rules).

For the purposes of these basic safety instructions, "skilled technical personnel" means persons who are familiar with the installation, mounting, commissioning and operation of the product and have the qualifications needed for the performance of their functions.

2. Intended use

Drive converters are components designed for inclusion in electrical installations or machinery.

In case of installation in machinery, commissioning of the drive converter (i.e. the starting of normal operation) is prohibited until the machinery has been proved to conform to the provisions of the EC directive 89/392/EEC (Machinery Safety Directive - MSD). Account is to be taken of EN 60204.

Commissioning (i.e. the start of normal operation) is admissible only where conformity with the EMC directive (89/336/EEC) has been established.

The drive converters meet the requirements of the low-voltage directive 73/23/EEC. They are subject to the harmonized standards of the series prEN 50178/DIN VDE 0160 in conjunction with EN 60439-1/DIN VDE 0660 Part 500 and EN 60146/DIN VDE 0558.

The technical data as well as information concerning the supply conditions shall be taken from the rating plate and from the documentation and shall be strictly observed.

3. Transport, storage

The instructions for transport, storage and proper use shall be complied with.

The climatic conditions shall be in conformity with prEN

4. Installation

The installation and cooling of the appliances shall be in accordance with the specifications in the pertinent documentation.

The drive converters shall be protected against excessive strains. In particular, no components must be bent and/or isolating distances altered in the course of transportation or handling. No contact shall be made with electronic components and contacts.

Drive converters contain electrostatic sensitive components which are liable to damage through improper use. Electronic components must not be mechanically damaged or destroyed (potential health risks)

5. Electrical connection

When working on live drive converters, the applicable national accident prevention rules (e.g. VBG 4) must be complied with.

The electrical installation shall be carried out in accordance with the relevant requirements (e.g. cross-sectional areas of conductors, fusing, PE connection). For further information, see documentation.

Instructions for the installation in accordance with EMC requirements, such as screening, grounding, location of filters and wiring, are contained in the drive converter documentation. They must always be complied with, also for drive converters bearing a CE marking. Observance of the limit values required by the EMC law is the responsibility of the manufacturer of the installation or machine.

6. Operation

Installations which include drive converters shall be equipped with additional monitoring and protective devices in accordance with the relevant applicable safety requirements, e.g. Act respecting technical equipment, accident prevention rules, etc. Changes to the drive converters by means of the operating software are permissible.

After disconnection of the drive converters from the voltage supply, live appliance parts and power terminals must not be touched immediately because of possibly energized capacitors. In this regard, the corresponding signs and markings on the drive converter must be respected.

During operation, all covers and doors shall be kept closed.

7. Maintenance and servicing

The manufacturer's documentation shall be followed.

Keep these safety instructions in a safe place!

10.98 Description

2 Description

Range of application

The inverter is a power electronics component for feeding highly dynamic three-phase drives in the output range from 2.2 kW to 37 kW.

The unit can be operated from a DC system with a voltage between 510 V and 650 V.

The inverter enables a three-phase system with a variable output frequency between 0 Hz and 400 Hz to be generated from the DC link direct voltage with the pulse width modulation method (PWM).

The internal DC 24 V voltage is supplied through an integral power supply unit from the DC link.

The unit is controlled by the internal closed-loop electronics, consisting of a micro-processor and a digital signal processor (DSP). The functions are provided by the unit software.

Operator control is via the PMU operator control panel, the user-friendly OP1S operator control panel, the terminal strip or via the serial interfaces of a bus system. For this purpose, the unit is provided with a number of interfaces and six slots for the use of optional boards.

Resolvers, encoders, pulse encoders and multiturn encoders can be used as encoders on the motor.




Fig. 2-1 Circuit principle of the inverter

NOTE

With option L33 "Compact unit without DC fuses" the DC fuses are replaced by conductive connections.

MAN Westical Still Still

01.2000 First Start-up

3 First Start-up

Unpack and check the units



Mount the unit and install optional boards which have not yet been fitted



Form the DC link capacitors, if necessary After removing the packaging, check that the unit is intact and undamaged. Only intact units may be started up. Please also check that the unit is complete, that the correct optional boards are fitted, and that the technology option has been released, if ordered.

See section "Transport, Storage, Unpacking"

See section

"Installation"

Retrofit any optional boards which have not yet been installed, if necessary. Then install the units taking into and "Installation account the requirements at the point of installation and in Conformance

> See section "Forming"

with EMC Regulations"

If the DC link of the unit was de-energized for more than one year, you have to newly form the DC link capacitors

Connect the protective conductor, the power cables or buses and, if present, the ext. 24 V supply



Connect the control cables, communication cables, encoder cables and motor cables



Please connect, starting with the protective conductor, the power cables or DC link buses and, if present, the external 24 V supply. Pay attention to EMC instructions when laying the cables. Please do not at this stage connect any control, communication, encoder and motor cables (exception: cable for connecting up an OP1S, if parameterization is to be effected via the OP1S).

Please connect the remaining control, communication, encoder and motor cables. Pay attention to the EMC instructions when laying the cables.



the EMC instructions.

The encoder connector may not be plugged in or unplugged with the power

See section "Connecting-up" and "Installation in Conformance with EMC Regulations"

See section "Connecting-up" and "Installation in Conformance with EMC Regulations"

Power up the external 24 V supply or the line voltage



If necessary, carry out parameter reset to factory setting

After checking that the cabling has been correctly connected and that it sits properly, power up the external 24 V supply or the line voltage. After the electronics power supply has been started, the unit initializes itself. The action can take several seconds. The drive status is subsequently shown on the PMU.

If the PMU does not show status °005 after completion of the unit initialization, or if the unit has already been parameterized before, you should carry out a parameter "Parameterization" reset to factory setting.

See section



First Start-up 01.2000

Parameterizing by download or with parameter modules

See section "Parameterization"



Function test

After checking the unit and the cabling once more, power up the line voltage or DC bus voltage, if you have not already done so, and perform a function test according to your parameterization.

WARNING



It must be ensured that no danger for persons and equipment can occur by energizing the power and the unit. It is recommended not to couple the driven machine until the function test has been successfully completed.

lacktriangle

Further start-up and parameterization according to your specific requirements

4 Transport, Storage, Unpacking

The units and components are packed in the manufacturing plant corresponding to that specified when ordered. A packing label is located on the outside of the packaging. Please observe the instructions on the packaging for transport, storage and professional

handling.

Transport Vibrations and jolts must be avoided during transport. If the unit is

damaged, you must inform your shipping company immediately.

Storage The units and components must be stored in clean, dry rooms.

Temperatures between -25 °C (-13 °F) and +70 °C (158 °F) are permissible. Temperature fluctuations must not be more than 30 K per

hour.

NOTE If the storage period of one year is exceeded, the unit must be newly

formed. See Section "Forming".

Unpacking The packaging comprises board and corrugated paper. It can be

disposed of corresponding to the appropriate local regulations for the disposal of board products. The units and components can be installed and commissioned after they have been unpacked and checked to

ensure that everything is complete and that they are not damaged.

MAN Westical Still Still

10.98 Installation

5 Installation

5.1 Installing the unit

WARNING



Safe converter operation requires that the equipment is mounted and commissioned by qualified personnel taking into account the warning information provided in these Operating Instructions.

The general and domestic installation and safety regulations for work on electrical power equipment (e.g. VDE) must be observed as well as the professional handling of tools and the use of personal protective equipment.

Death, severe bodily injury or significant material damage could result if these instructions are not followed.

Clearances

When positioning the units, it must be observed that the DC link connection is located at the top section of the unit and the motor connection at the lower section of the unit.

The units can be mounted flush with each other.

In order to ensure an adequate supply of cooling air, a clearance of 100 mm must be left at the top of the unit and 250 mm at the bottom of the unit respectively to components which may considerably affect the flow of cooling air.

When mounting in switch cabinets, the cabinet cooling must be dimensioned according to the dissipated power. Please refer to the Technical Data in this regard.

Requirements at the point of installation

♦ Foreign particles

The units must be protected against the ingress of foreign particles as otherwise their function and operational safety cannot be ensured.

◆ Dust, gases, vapors

Equipment rooms must be dry and dust-free. Ambient and cooling air must not contain any electrically conductive gases, vapors and dusts which could diminish the functionality. If necessary, filters should be used or other corrective measures taken.

Cooling air

The ambient climate of the units must not exceed the values of DIN IEC 721-3-3 class 3K3. For cooling air temperatures of more than 40°C (104°F) and installation altitudes higher than 1000 m, derating is required.

Installation 10.98




Fig. 5-1 Minimum clearances for cooling

Mounting

The unit is mounted directly to a mounting surface, for which you require the following:

- ◆ G-type mounting rail according to EN50035 with screws for fixing at the top
- One M6 screw for types A to C, two M6 screws for type D, for fixing at the bottom
- Dimension drawing for types A, B and for types C, D.

10.98 Installation




Fig. 5-2 Dimension drawings for installation of types A, B




Fig. 5-3 Dimension drawings for installation of types C,D

Installation 10.98

5.2 Installing the optional boards

WARNING

The boards may only be replaced by qualified personnel.



Slots

It is not permitted to withdraw or insert the boards under voltage.

A maximum of six slots are available in the electronics box of the unit for installing optional boards. The slots are designated with the letters A to G. Slot B is not provided in the electronics box. It is used in units of the Compact PLUS type of construction.

If you wish to use slots D to G, you will additionally require the following:

- Bus expansion LBA (Local Bus Adapter), which is used for mounting the CU board and up to two adaption boards, and
- An adaption board (ADB Adaption Board) on which up to two optional boards can be mounted.

The slots are situated at the following positions:

♦ Slot A	CU board	Position: top
♦ Slot C	CU board	Position: bottom
♦ Slot D	Adaption board at mounting position 2	Position: top
♦ Slot E	Adaption board at mounting position 2	Position: bottom
♦ Slot F	Adaption board at mounting position 3	Position: top
♦ Slot G	Adaption board at mounting position 3	Position: bottom




Fig. 5-4 Position of the slots in the electronics box

NOTE

Mounting position 2 can be used for technology boards (T100, T300).

10.98 Installation

WARNING



The unit has hazardous voltage levels up to 5 minutes after it has been powered down due to the DC link capacitors. The unit must not be opened until at least after this delay time.

CAUTION



The optional boards contain components which could be damaged by electrostatic discharge. These components can be very easily destroyed if not handled with caution. You must observe the ESD cautionary measures when handling these boards.

Disconnecting the unit from the supply

Disconnect the unit from the incoming power supply (AC or DC supply) and de-energize the unit. Remove the 24 V voltage supply for the electronics.

Open the front panel.

Preparing installation

Remove the CU board or the adaption board from the electronics box as follows:

- Disconnect the connecting cables to the CU board or to the optional boards.
- Undo the two fixing screws on the handles above and below the CU board or the adaption board.
- Pull the CU board or the adaption board out of the electronics box using the handles.
- Place the CU board or the adaption board on a grounded working surface.

Installing the optional board

Insert the optional board from the right onto the 64-pole system connector on the CU board or on the adaption board. The view shows the installed state.

Screw the optional board tight at the fixing points in the front section of the optional board using the two screws attached.

Re-installing the unit

Re-install the CU board or the adaption board in the electronics box as follows:

◆ Insert the CU board into mounting position 1 and the adaption board into mounting position 2 or 3.

NOTE

Mounting position 3 cannot be used until at least one adaption board has been installed at mounting position 2. Boards should first be installed in mounting position 2, before mounting position 3 is used.

 Secure the CU board/adaption board at the handles with the fixing screws.

Re-connect the previously removed connections.

Check that all the connecting cables and the shield sit properly and are in the correct position.

MAN Westical Still Still

6 Installation in Conformance with EMC Regulations

The following contains a summary of general information and guidelines which will make it easier for you to comply with EMC and CE regulations.

- ◆ Ensure that there is a conductive connection between the housing of the converters or inverters and the mounting surface. The use of mounting surfaces with good conducting properties (e.g. galvanized steel plate) is recommended. If the mounting surface is insulated (e.g. by paint), use contact washers or serrated washers.
- All of the metal cabinet parts must be connected through the largest possible surface area and must provide good conductivity.
 If necessary, use contact washers or serrated washers.
- ◆ Connect the cabinet doors to the cabinet frame using grounding strips which must be kept as short as possible.
- For the connection between converter/inverter and motor, use shielded cables which have to be grounded on both sides over a large surface area.
 If the motor terminal box is of plastic, additional grounding strands
 - have to be inserted.
- The shield of the motor supply cable must be connected to the shield connection of the converter and to the motor mounting panel through the largest possible surface area.
- The motor cable shield must not be interrupted by output reactors, fuses or contactors.
- All signal cables must be shielded. Separate the signal cables according to signal groups.
 Do not route cables with digital signals unshielded next to cables with analog signals. If you use a common signal cable for both, the individual signals must be shielded from each other.
- Power cables must be routed separately away from signal cables (at least 20 cm apart). Provide partitions between signal cables and power cables. The partitions must be grounded.
- Connect the reserve cables/conductors to ground at both ends to achieve an additional shielding effect.
- Lay the cables close to grounded plates as this will reduce the injection of undesired signals.

- ♦ Eliminate any unnecessary cable lengths because these will produce additional coupling capacitances and inductances.
- Use cables with braided shields. Cables with foil shields have a shielding effect which is worse by a factor of five.
- Contactor operating coils that are connected to the same supply network as the inverter or that are located in close proximity of the inverter must be connected to overvoltage limiters (e.g. RC circuits, varistors).

You will find further information in the brochure "Installation Instructions for EMC-correct Installation of Drives" (Order No.: 6SE7087-6CX87-8CE0).

10.99 Connecting-up

7 Connecting-up

WARNING



SIMOVERT MASTERDRIVES units are operated at high voltages. The equipment must be in a no-voltage condition (disconnected from the supply) before any work is carried out!

Only professionally trained, qualified personnel must work on or with the units.

Death, severe bodily injury or significant property damage could occur if these warning instructions are not observed.

Hazardous voltages are still present in the unit up to 5 minutes after it has been powered down due to the DC link capacitors. Thus, the appropriate delay time must be observed before working on the unit or on the DC link terminals.

The power terminals and control terminals can still be live even when the motor is stationary.

If the DC link voltage is supplied centrally, the converters must be reliably isolated from the DC link voltage!

When working on an opened unit, it should be observed that live components (at hazardous voltage levels) can be touched (shock hazard).

The user is responsible that all the units are installed and connected-up according to recognized regulations in that particular country as well as other regionally valid regulations. Cable dimensioning, fusing, grounding, shutdown, isolation and overcurrent protection should be particularly observed.

Connecting-up 10.99




Fig. 7-1 Connection overview of types A, B, C

10.99 Connecting-up




Fig. 7-2 Connection overview of type D

NOTE

An external aux. voltage of 230 V AC must be connected to F101 and F102 in the case of type of construction D. The aux. voltage is needed for the fan in the unit.

Connecting-up 10.99

7.1 Power connections

WARNING



If the input and output terminals are mixed up, the unit will be destroyed!

If the DC link terminals are mixed up or short-circuited, the converter will be destroyed!

The unit must not be operated via an earth leakage circuit-breaker (DIN VDE 0160).

Protective conductor

The protective conductor must be connected up both on the mains side and on the motor side.

On account of leakage currents through the interference-suppression capacitors, a minimum cross-section of 10 mm² must be used in accordance with VDE 0160. If mains connections with cross-sections less than 10 mm² are used, the following measures can be applied.

If the unit is mounted on a grounded mounting surface via a conductive connection, the protective conductor cross-section can be the same as that of the supply-cable conductor.

In the case of insulated installation or a poor conductive connection to the mounting surface, a separate protective conductor with a cross-section of 10 mm² can be connected up instead of the protective conductor of the mains connection.

Direct volta	Direct voltage DC 510 V to 650 V											
Order	Rated			lr	Infeed side				Motor side			
number	direct cur- rent	Cross- section		Reco mend fuse	ded	Internal D	C fus	е	Rated output		Cross- section	
6SE70		VDE	AWG	gR (S	SITOR)	Туре			voltage	current	VDE	AWG
	[A]	[mm²]		[A]	3NE	FWP	[V]	[A]	[V]	[A]	[mm²]	
16-1TA51	7.3	1.5	16	25	8015	25A14F	700	25	0 to 480	6.1	1.5	16
18-0TA51	9.5	1.5	16	25	8015	50A14F	700	50	0 to 480	8.0	1.5	16
21-0TA51	12.1	1.5	16	25	8015	50A14F	700	50	0 to 480	10.2	1.5	16
21-3TB51	15.7	4	10	50	8017	50A22F	700	50	0 to 480	13.2	2.5	14
21-8TB51	20.8	4	10	50	8017	50A22F	700	50	0 to 480	17.5	2.5	14
22-6TC51	30.4	10	6	80	8020	100A22F	700	100	0 to 480	25.5	6	8
23-4TC51	40.5	10	6	80	8020	100A22F	700	100	0 to 480	34.0	10	6
23-8TD51	44.6	16	4	125	8022	100A22F	700	100	0 to 480	37.4	16	4
24-7TD51	55.9	25	2	125	8022	100A22F	700	100	0 to 480	47.0	16	4
26-0TD51	70.2	35	0	160	8024	80A22F	700	2x80	0 to 480	59.0	25	2
27-2TD51	85.7	30	0	160	8024	80A22F	700	2x80	0 to 480	72.0	25	2

AWG: American Wire Gauge

Table 7-1 Cross-sections, fuses

10.99 Connecting-up

NOTE

 The connection cross-sections are calculated for copper cables at 40 °C (104 °F) ambient temperature (according to DIN VDE 0298 Part 4 / 02.88 Group 5).

In the case of a rated direct voltage of 510 V, additional fuses are not necessary on the infeed side due to integrated DC fuses in the unit, provided that the connecting cables to the DC bus are laid short-circuit proof and that there is no risk of the cables being overloaded by other consumers.

Maximum possible connection crosssections

Туре	Order number	Finely-stranded		Multi-strar	nded, solid
		mm²	AWG	mm²	AWG
Α	6SE702A_1	2.5 to 10	12 to 6	2.5 to 16	12 to 4
В	6SE702B_1	2.5 to 10	12 to 6	2.5 to 16	12 to 4
С	6SE702C_1	4 to 16	6 to 4	10 to 25	6 to 2
D	6SE702D_1	10 to 35	6 to 2	10 to 50	6 to 0

Table 7-2 Maximum possible connection cross-sections

DC link connection

The connection for the DC link is provided on the top of the unit on a terminal block.

0	0	0	0	0	0
U1	V1	W1	PE1	С	D
L1	L2	L3	\bigsigma	L+	L-

Terminal	Designation	Meaning	Range
1	U1 / L1	These terminals	
2	V1/L2	are not	
3	W1/L3	internally connected	
4	PE1	Protective conductor connection	
5	C/L+	DC link voltage +	DC 510 - 650 V
6	D/L-	DC link voltage -	DC 510 - 650 V

Terminal 1 is at the left when installed.

Table 7-3 DC link connection

X2 – Motor connection

T1	T2	Т3	(
U2	V2	W2	PE2
0	0	Ø	0

The motor connection is located at the bottom of the unit.

	Terminal	Designation	Meaning	Range
1	1	U2 / T1	Phase U2 / T1	3AC 0 – 480 V
	2	V2 / T2	Phase V2 / T2	3AC 0 – 480 V
	3	W2/T3	Phase W2 / T3	3AC 0 - 480 V
	4	PE2	Protective conductor connection	

Terminal 1 is at the left when installed.

Table 7-4 Motor connection

Connecting-up 10.99

NOTE


For inverters of type D, a fan is installed with a voltage of 230 V for which an external auxiliary voltage has to be connected up at fuses F101 and F102.

X9 - external DC24 V supply, safe OFF, main contactor control The 9-pole terminal strip is used for connecting up a 24 V voltage supply and for connecting up a main or bypass contactor and for the "Safe OFF" function.

The voltage supply is required if the inverter is connected up via a main or bypass contactor.

The connections for the contactor control are floating.

The "Safe OFF" function ensures that no rotating field can occurr at the motor terminals, i.e. the motor cannot rotate. By opening the jumper between terminals X9.5 and X9.6 (through an external contact), the "Safe OFF" function is activated. The inverter is delivered with jumpered terminals X9.5 and X9.6.



Terminal	Designation	Meaning	Range
9	Main contactor control	Main contactor control	DC30 V, 0.5 A
8	n.c.	Not connected	
7	Main contactor control	Main contactor control	
6	Safe OFF	"Safe OFF" control	DC 30 V
5	Safe OFF	"Safe OFF" control	1030 mA
4	Safe OFF	"Safe OFF" checkback	DC30 V
3	Safe OFF	"Safe OFF" checkback	2 A
2	0 V	Reference potential	0 V
1	+24 V (in)	24 V voltage supply	DC 24 V ≤ 2.5 A

Connectable cross-section: 1.5 mm² (AWG 16)

Terminal 1 is at the front when installed.

Table 7-5 Connection of external aux. voltage supply DC 24 V, safe OFF, main contactor control

WARNING

The power terminals may still be live even if the "Safe OFF" function is activated!

The relay on PEU -X9:7.9 is only suitable for switching voltages up to 30 V with a 9-pole terminal strip!

Connections on optional boards

Each optional board is provided with additional connections which are necessary for the function of the optional board - encoder connections, bus connections or additional terminals.

You will find detailed information on the connections of the optional boards in the corresponding documentation.

10.99 Connecting-up

7.2 Control connections

Standard connections

In the basic version, the unit has the following control connections on the CUMC:

- ♦ Serial interface (RS232 / RS485) for PC or OP1S (interface 1)
- One serial interface (USS bus, RS485) (interface 2)
- One control terminal strip with digital and analog inputs and outputs.




Fig. 7-3 View of the CUMC

Connecting-up 10.99




Fig. 7-4 Overview of the standard connections

01.2000 Connecting-up

X101 – Control terminal strip

The following connections are provided on the control terminal strip:

- 4 optionally parameterizable digital inputs and outputs
- ♦ 2 digital inputs
- ♦ 1 analog input
- ♦ 1 analog output
- 24 V aux. voltage supply (max. 150 mA, output only!) for the inputs and outputs

CAUTION



If the digital inputs are supplied from an external 24 V supply, this must be referenced to frame X101.2. Terminal X101.1 (P24 AUX) may **not** be connected with the 24V supply.

A	1	•
A	2	•
A	3	•
A	4	•
A	5	•
A	6	•
A	7	•
A	8	•
A	9	•
A	10	•
A	11	•
A	12	•

Terminal	Designation	Meaning	Range
1	P24 AUX	Aux. voltage supply	DC 24 V / 150 mA
2	M24 AUX	Reference potential	0 V
3	DIO1	Digital input/output 1	24 V, 10 mA / 20 mA
4	DIO2	Digital input/output 2	24 V, 10 mA / 20 mA
5	DIO3	Digital input/output 3	24 V, 10 mA / 20 mA
6	DIO4	Digital input/output 4	24 V, 10 mA / 20 mA
7	DI5	Digital input 5	24 V, 10 mA
8	DI6	Digital input 6	24 V, 10 mA
9	Al–	Analog input –	11 bit + sign differential input:
10	Al+	Analog input +	\pm 10 V / Ri = 40 k Ω
11	AO	Analog output	11 bit + sign ± 10 V, 5 mA
12	M AO	Ground analog output	

Connectable cross-section: 0.14 mm² to 1.5 mm² (AWG 16)

Terminal 1 is at the top when installed.

Table 7-6 Control terminal strip

Connecting-up 10.99

X103 - 10 V voltage output, SCom1, SCom2

24252627

The following connections are provided on the control terminal strip:

- 10 V aux. voltage (max. 5 mA) for the supply of external potentiometers
- ◆ 2 serial interfaces SCom1 and SCom2 (USS / RS485)

Terminal	Designation	Meaning	Range
23	P10 V	+10 V supply for ext. potentiometer	+10 V ±1.3 %, Imax = 5 mA
24	N10 V	-10 V supply for ext. potentiometer	$-10 V \pm 1.3 \%$, $lmax = 5 mA$
25	RS485 P (SCom2)	USS bus connection SCom2	RS485
26	RS485 N (SCom2)	USS bus connection SCom2	RS485
27	RS485 P (SCom1)	USS bus connection SCom1	RS485
28	RS485 N (SCom1)	USS bus connection SCom1	RS485

Connectable cross-section: 0.14 mm² to 1.5 mm² (AWG 16)

The terminals 23 and 24 are short-circuit proof.

Terminal 23 is at the top when installed.


Table 7-7 Control terminal strip X103


X300 - Serial interface

Either an OP1S or a PC can be connected up via the 9-pole SUB D socket.

The 9-pole SUB D socket is internally coupled with the USS bus, with the result that it is possible to exchange data with further converters and inverters which are linked via the USS bus.

Pin	Name	Meaning	Range
1	n.c.	Not connected	
2	RS232 RxD	Receive data via RS232	RS232
3	RS485 P	Data via RS485	RS485
4	Boot	Control signal for software update	Digital signal, low active
5	M5V	Reference potential to P5V	0 V
6	P5V 5 V aux. voltage supply		+5 V, Imax = 200 mA
7	RS232 TxD Transmit data via RS232		RS232
8	RS485 N	Data via RS485 RS485	
9	M_RS232/485	Digital ground (choked)	





10.99 Connecting-up

Switch settings

Switch	Meaning	
S1	SCom1 (X300): Bus terminating resistor	
• open	Resistor open	
• closed	Resistor closed	
S2	SCom2 (X101/10,11): Bus terminating resistor	
• open	Resistor open	•
• closed	Resistor closed	

7.3 Fan fuses

Line voltage DC 510 V to 660 V				
Order number		Fan fuse (F1 / F2)		
6SE7023-8TD51		FNQ-R-2		
6SE7024-7TD51		FNQ-R-2		
6SE7026-0TD51		FNQ-R-2		
6SE7027-2TD51		FNQ-R-2		
Manufacturer:	FNQ-R	Bussmann		

Table 7-9 Fan fuses

MAN Westical Still Still

8 Parameterization

The functions stored in the units are adapted to your specific application by means of parameters. Every parameter is clearly identified by its parameter name and its parameter number. In addition to the parameter name and number, many parameters also have a parameter index. These indices enable several values to be stored for a parameter under one parameter number.

Parameter numbers consist of a letter and a three-digit number. The upper-case letters P, U, H and L represent the parameters which can be changed, and the lower-case letters r, n, d and c represent the visualization parameters which cannot be changed.

Examples

DC Bus Volts r006 = 541 Parameter name: DC Bus volts

Parameter number: r006

Parameter index: Does not exist

Parameter value: 541 V

Src ON/OFF1 P554.2 = 20 Parameter name: Src ON/OFF1

Parameter number: P554
Parameter index: 2
Parameter value: 20

Parameters can be input as follows:

 Via the PMU parameterizing unit which is permanently mounted on the front of the units,

- Via the user-friendly optional OP1S operator control panel or
- ♦ Via a PC and the SIMOVIS service program.

The parameters stored in the units can only be changed under certain conditions. The following preconditions must be satisfied before they can be changed.

- ◆ The parameter must be a changeable parameter. (Designated by upper-case letters in the parameter number).
- Parameter access must be granted.
 (P053 = 6 for parameterizing via the PMU or the OP1S).
- The unit must be in a status which permits parameters to be changed. (Carry out initial parameterization only in powered-down status).
- The lock and key mechanism must not be activated (Deactivation by parameter reset to factory setting).

Parameterization 10.99

8.1 Parameter input via the PMU




Fig. 8-1 PMU parameterizing unit

Key	Significance	Function	
	ON key	For energizing the drive (enabling motor activation).	
		If there is a fault: For returning to fault display	
0	OFF key	For de-energizing the drive by means of OFF1, OFF2 or OFF3 (P554 to 560) depending on parameterization.	
	Reversing key	For reversing the direction of rotation of the drive. The function must be enabled by P571 and P572	
Р	Toggle key	 For switching between parameter number, parameter index and parameter value in the sequence indicated (command becomes effective when the key is released). If fault display is active: For acknowledging the fault 	
	Raise key	For increasing the displayed value:	
		Short press = single-step increase	
		Long press = rapid increase	
	Lower key	For lowering the displayed value:	
	•	Short press = single-step decrease	
		Long press = rapid decrease	
P +	Hold toggle key	If parameter number level is active: For jumping back and forth	
	and depress	between the last selected parameter number and the operating	
	raise key	display (r000)	
		If fault display is active: For switching over to parameter number level	
		If parameter value level is active: For shifting the displayed value one digit to the right if parameter value cannot be displayed with 4 figures (left-hand figure flashes if there are any further invisible figures to the left)	
P + 🗸	Hold toggle key and depress	If parameter number level is active: For jumping directly to the operating display (r000)	
7	lower key	If parameter value level is active: For shifting the displayed value one digit to the left if parameter value cannot be displayed with 4 figures (right-hand figure flashes if there are any further invisible figures to the right)	

Table 8-1 Operator control elements on the PMU

Toggle key (P key)

As the PMU only has a four-digit seven-segment display, the 3 descriptive elements of a parameter


- Parameter number,
- Parameter index (if parameter is indexed) and
- ◆ Parameter value

cannot be displayed at the same time. For this reason, you have to switch between the individual descriptive elements by depressing the toggle key. After the desired level has been selected, adjustment can be made using the raise key or the lower key.

With the toggle key, you can change over:

- from the parameter number to the parameter index
- from the parameter index to the parameter value
- from the parameter value to the parameter number

If the parameter is not indexed, you can jump directly from the parameter number to the parameter value.



NOTE


If you change the value of a parameter, this change generally becomes effective immediately. It is only in the case of acknowledgement parameters (marked in the parameter list by an asterisk ' * ') that the change does not become effective until you change over from the parameter value to the parameter number.

Parameter changes made using the PMU are always safely stored in the EEPROM (protected in case of power failure) once the toggle key has been depressed.

Example

The following example shows the individual operator control steps to be carried out on the PMU for a parameter reset to factory setting.


Set P053 to 0002 and grant parameter access via PMU



Select P060




Set P060 to 0002 and select "Fixed settings" menu



Select P970



Set P970 to 0000 and start parameter reset



8.2 Parameter input via the OP1S

The operator control panel (OP1S) is an optional input/output device which can be used for parameterizing and starting up the units. Plaintext displays greatly facilitate parameterization.

The OP1S has a non-volatile memory and can permanently store complete sets of parameters. It can therefore be used for archiving sets of parameters. The parameter sets must be read out (upread) from the units first. Stored parameter sets can also be transferred (downloaded) to other units.

The OP1S and the unit to be operated communicate with each other via a serial interface (RS485) using the USS protocol. During communication, the OP1S assumes the function of the master whereas the connected units function as slaves.

The OP1S can be operated at baud rates of 9.6 kBd and 19.2 kBd, and is capable of communicating with up to 32 slaves (addresses 0 to 31). It can therefore be used both in a point-to-point link (e.g. during initial parameterization) and within a bus configuration.

The plain-text displays can be shown in one of five different languages (German, English, Spanish, French, Italian). The language is chosen by selecting the relevant parameter for the slave in question.

Order numbers

Components	Order Number
OP1S	6SE7090-0XX84-2FK0
Connecting cable 3 m	6SX7010-0AB03
Connecting cable 5 m	6SX7010-0AB05
Adapter for installation in cabinet door incl. 5 m cable	6SX7010-0AA00

NOTE

The parameter settings for the units connected to the OP1S are given in the corresponding documentation of the unit (Compendium).




Fig. 8-2 View of the OP1S




Fig. 8-3 The OP1S directly connected to the unit

NOTE

In the as-delivered state or after a reset of the parameters to the factory setting, a point-to-point link can be adopted with the OP1S without any further preparatory measures and parameterization can be commenced.

Key	Significance	Function
I	ON key	For energizing the drive (enabling motor activation). The function must be enabled by means of parameterization.
0	OFF key	For de-energizing the drive by means of OFF1, OFF2 or OFF3, depending on parameterization. This function must be enabled by means of parameterization.
Jog	Jog key	For jogging with jogging setpoint 1 (only effective when the unit is in the "ready to start" state). This function must be enabled by means of parameterization.
	Reversing key	For reversing the direction of rotation of the drive. The function must be enabled by means of parameterization.
Р	Toggle key	For selecting menu levels and switching between parameter number, parameter index and parameter value in the sequence indicated. The current level is displayed by the position of the cursor on the LCD display (the command comes into effect when the key is released).
		For conducting a numerical input
Reset	Reset key	 For leaving menu levels If fault display is active, this is for acknowledging the fault. This function must be enabled by means of parameterization.
	Raise key	For increasing the displayed value: Short press = single-step increase Long press = rapid increase If motorized potentiometer is active, this is for raising the setpoint. This function must be enabled by means of parameterization
	Lower key	 For lowering the displayed value: Short press = single-step decrease Long press = rapid decrease If motorized potentiometer is active, this is for lowering the setpoint. This function must be enabled by means of parameterization.
+/-	Sign key	For changing the sign so that negative values can be entered
9 to 0	Number keys	Numerical input

Table 8-2 Operator control elements of the OP1S


NOTE

If you change the value of a parameter, the change does not become effective until the toggle key (P) is pressed.

Parameter changes made using the OP1S are always stored safely in the EEPROM (protected in case of power failure) once the toggle key (P) has been pressed.

Some parameters may also be displayed without a parameter number, e.g. during quick parameterization or if "Fixed setting" is selected. In this case, parameterization is carried out via various sub-menus.


Example of how to proceed for a parameter reset.



Selection of fixed setting



Selection of factory setting



Start of factory setting

NOTE

It is not possible to start the parameter reset in the "Run" status.

8.3 Parameter reset to factory setting


The factory setting is the defined initial state of all parameters of a unit. The units are delivered with this setting.

You can restore this initial state at any time by resetting the parameters to the factory setting, thus canceling all parameter changes made since the unit was delivered.

The parameters for defining the power section and for releasing the technology options and the operating hours counter and fault memory are not changed by a parameter reset to factory setting.

Parameter number	Parameter name
P070	Order No. 6SE70
P072	Rtd Drive Amps
P073	Rtd Drive Power
P366	Select FactSet

Table 8-3 Parameters which are not changed by the factory setting



Grant parameter access

6: Parameter changes permitted via PMU and serial interface SCom1 (OP1S and PC)

Menu selection "Fixed settings"

Select desired factory setting

0: Standard

Note: This parameter was correctly set prior to despatch of the unit and only needs to be changed in exceptional

Start parameter reset

- 0: Parameter reset
- : No parameter change

Unit carries out parameter reset and goes into status 5 "Drive setting".

Fig. 8-4 Sequence for parameter reset to factory setting


8.4 Parameterizing by download

Downloading with OP1S

The OP1S operator control panel is capable of upreading parameter sets from the units and storing them. These parameter sets can then be transferred to other units by download. Downloading with the OP1S is thus the preferred method of parameterizing replacement units in a service case.

During downloading with the OP1S, it is assumed that the units are in the as-delivered state. The parameters for the power section definition are thus not transferred (see section "Detailed parameterization, power section definition"). If a PIN has been entered to release optional technology functions, this is also not overwritten during downloading.


With the "OP: Download" function, a parameter set stored in the OP1S can be written into the connected slave. Starting from the basic menu, the "OP: Download" function is selected with "Lower" or "Raise" and activated with "P".



Example: Selecting and activating the "Download" function

Now one of the parameter sets stored in the OP1S has to be selected using the "Lower" or "Raise" keys (displayed in the second line). The selected ID is confirmed with the "P" key. Now the slave ID can be displayed with "Lower" or "Raise". The slave ID contains various characteristic features of the unit such as rated output, order number, software version, etc.


The "Download" procedure is then started with the "P" key. During download, the OP1S displays the parameter currently being written.



Example: Confirming the ID and starting the "Download" procedure

With "Reset", the procedure can be stopped at any time. If downloading has been fully completed, the message "Download ok" appears and the display returns to the basic menu.

After the data set to be downloaded has been selected, if the identification of the stored data set does not agree with the identification of the connected unit, an error message appears for approximately 2 seconds. The operator is then asked if downloading is to be discontinued.



Yes: Downloading is discontinued.
No: Downloading is carried out.

8.5 Parameterizing with parameter modules

Pre-defined, function-assigned parameter modules are stored in the units. These parameter modules can be combined with each other, thus making it possible to adjust your unit to the desired application by just a few parameter steps. Detailed knowledge of the complete parameter set of the unit is not required.

Parameter modules are available for the following function groups:


- 1. Motors
- 2. Motor encoders
- 3. Control types
- 4. Setpoint and command sources

Parameterization is effected by selecting a parameter module from each function group and then starting quick parameterization.

Depending on your selection, the necessary unit parameters are set to produce the desired control functionality. The parameters necessary for fine adjustment of the control structure are automatically adopted in the user menu.

NOTE

If parameter changes have already been carried out on the unit, it is recommended that you carry out a parameter reset to the factory setting prior to performing "Quick parameterization".



Select "Quick parameterization" menu

Enter the unit supply voltage in V

(direct voltage for DC supply, rms value of AC voltage for AC supply)

Select type of motor


- 0: No motor connected
- 1: Synchronous servomotor 1FT6/1FK6
- 2: Induction servomotor 1PH7(=1PA6)/1PL6/1PH4

Enter the code number for the connected 1FK6/1FT6 motor (for list see attachment)

Enter the code number for the connected 1PH7(=1PA6) /1PH4 /1PL6 motor (for list see attachment)

Start calculation of motor model

(no longer necessary from V1.40 onwards)



P367 = ?

P115 = 1

- Select motor encoder
 0: Without encoder
 - 1: 2-pole resolver
 - 2: Resolver with pole pair number of motor
 - 3: Encoder 2048/rev.
 - 4: Multiturn encoder 2048/rev.
 - 5: Pulse encoder 1024/rev.

Select type of control for quick parameterization

- 0: V/f open-loop control
- 2: Torque closed-loop control
- 3: Speed closed-loop control

P368 = ?


Select setpoint and command source


- 0: PMU
- 1: Analog and digital inputs on the terminal strip
- 2. Fixed setpoints and digital inputs on the terminal strip
- 3: Motorized potentiometer and digital inputs on terminal strip
- 4: USS1 (e.g. with SIMATIC)
- 5: SIMOLINK (SLB) (without fig.)
- 6: PROFIBUS (CBP) (without fig.)
- 7: OP1S and fixed setpoints via SCom1 (X300: PMU)





Enter the PROFIBUS address





Start quick parameterization

- 0: No parameter change
- 1: Parameter change according to selected combination of parameter modules

Note:

After the start, first of all an automatic factory setting is carried out with P366 = 0, then the relevant parameterization is performed.

Return to the user menu

Fig. 8-5 Sequence for parameterizing with parameter modules

Function diagram modules

Function diagram modules (function diagrams) are shown after the flow chart for parameter modules stored in the unit software. On the first few pages are the :


- setpoint and command sources, on the following pages are the
- analog outputs and the display parameters and the
- open-loop and closed-loop control types.

It is therefore possible to put together the function diagrams to exactly suit the selected combination of setpoint/command source and open/closed-loop control type. This will give you an overview of the functionality parameterized in the units and of the necessary assignment of the terminals.


The function parameters and visualization parameters specified in the function diagrams are automatically adopted in the user menu and can be visualized or changed there.


The parameter numbers of the user menu are entered in P360.

















8.6 Motor lists

1FK6 / 1FT6

Input in P096	Motor order-number (MLFB)	Speed n _n [1/min]	Torque T _n [Nm]	Current In [A]
1	1FK6032-6AK7	6000	0,8	1.5
2	1FK6040-6AK7	6000	0.8	1.8
3	1FK6042-6AF7	3000	2.6	2.4
4	1FK6060-6AF7	3000	4.0	3.1
5	1FK6063-6AF7	3000	6.0	4.9
6	1FK6080-6AF7	3000	6.8	5.3
7	1FK6083-6AF7	3000	10.5	7.8
8	1FK6100-8AF7	3000	12.0	9.0
9	1FK6101-8AF7	3000	15.5	10.8
10	1FK6103-8AF7	3000	16.5	11.6
11	1FT6031-4AK7_	6000	0.75	1.2
12	1FT6034-1AK73A 1FT6034-4AK7_	6000	1.4	2.1
13	1FT6041-4AF7_	3000	2.15	1.7
14	1FT6041-4AK7_	6000	1.7	2,4
15	1FT6044-1AF73A 1FT6044-4AF7_	3000	4.3	2.9
16	1FT6044-4AK7_	6000	3.0	4.1
17	1FT6061-6AC7_	2000	3.7	1.9
18	1FT6061-1AF73A 1FT6061-6AF7_	3000	3.5	2.6
19	1FT6061-6AH7_	4500	2.9	3.4
20	1FT6061-6AK7_	6000	2.1	3.1
21	1FT6062-6AC7_	2000	5.2	2.6
22	1FT6062-1AF73A 1FT6062-6AF7_	3000	4.6	3.4
23	1FT6062-6AH7_	4500	3.6	3.9
24	1FT6062-6AK7_	6000	2.1	3.2
25	1FT6064-6AC7_	2000	8.0	3.8
26	1FT6064-1AF73A 1FT6064-6AF7_	3000	7.0	4.9
27	1FT6064-6AH7_	4500	4.8	5.5
28	1FT6064-6AK7_	6000	2.1	3.5
29	1FT6081-8AC7_	2000	7.5	4.1
30	1FT6081-8AF7_	3000	6.9	5.6
31	1FT6081-8AH7_	4500	5.8	7.3
32	1FT6081-8AK7_	6000	4.6	7.7
33	33 1FT6082-8AC7_		11.4	6.6

Input in P096	Motor order-number (MLFB)	Speed n _n [1/min]	Torque T _n [Nm]	Current In [A]
34	1FT6082-1AF71A 1FT6082-8AF7_	3000	10.3	8.7
35	1FT6082-8AH7_	4500	8.5	11.0
36	1FT6082-8AK7_	6000	5.5	9.1
37	1FT6084-8AC7_	2000	16.9	8.3
38	1FT6084-1AF71A 1FT6084-8AF7_	3000	14.7	21.0
39	1FT6084-8AH7_	4500	10.5	12.5
40	1FT6084-8AK7_	6000	6.5	9.2
41	1FT6084-8SC7_	2000	23.5	12.5
42	1FT6084-8SF7_	3000	22.0	17.0
43	1FT6084-8SH7_	4500	20.0	24.5
44	1FT6084-8SK7_	6000	17.0	25.5
45	1FT6086-8AC7_	2000	23.0	10.9
46	1FT6086-1AF71A 1FT6086-8AF7_	3000	18.5	13.0
47	1FT6086-8AH7_	4500	12.0	12.6
48	1FT6086-8SC7_	2000	33.0	17.5
49	1FT6086-8SF7_	3000	31.0	24.5
50	1FT6086-8SH7_	4500	27.0	31.5
51	1FT6086-8SK7_	6000	22.0	29.0
52	1FT6102-8AB7_	1500	24.5	8.4
53	1FT6102-1AC71A 1FT6102-8AC7_	2000	23.0	11.0
54	1FT6102-8AF7_	3000	19.5	13.2
55	1FT6102-8AH7_	4500	12.0	12.0
56	1FT6105-8AB7_	1500	42.0	14.5
57	1FT6105-1AC71A 1FT6105-8AC7_	2000	38.0	17.6
58	1FT6105-8AF7_	3000	31.0	22.5
59	1FT6105-8SB7_	1500	57.0	21.5
60	1FT6105-8SC7_	2000	55.0	28.0
61	1FT6105-8SF7_	3000	49.0	35.0
62	1FT6108-8AB7_	1500	61.0	20.5
63	1FT6108-8AC7_	2000	55.0	24.5
64	1FT6108-8SB7_	1500	83.0	31.0
65	1FT6108-8SC7_	2000	80.0	39.0
66	1FT6132-6AB7_	1500	62.0	19.0
67	1FT6132-6AC7_	2000	55.0	23.0
68	1FT6132-6AF7_	3000	36.0	23.0

Input in P096	Motor order-number (MLFB)	Speed n _n [1/min]	Torque T _n [Nm]	Current In [A]
69	1FT6132-6SB7_	1500	100.0	36.0
70	1FT6132-6SC7_	2000	98.0	46.0
71	1FT6132-6SF7_	3000	90.0	62.0
72	1FT6134-6AB7_	1500	75.0	24.0
73	1FT6134-6AC7_	2000	65.0	27.0
74	1FT6134-6SB7_	1500	130.0	45.0
75	1FT6134-6SC7_	2000	125.0	57.0
76	1FT6134-6SF7_	3000	110.0	72.0
77	1FT6136-6AB7_	1500	88.0	27.0
78	1FT6136-6AC7_	2000	74.0	30.0
79	1FT6136-6SB7_	1500	160.0	55.0
80	1FT6136-6SC7_	2000	150.0	72.0
81	1FT6108-8SF7_	3000	70.0	53.0
82	1FK6033-7AF71	1)	1)	1)
83	1FK6043-7AF7_	3000	2.8	3,4
84	1FK6043-7AH7_ 2)	4500	2.6	4.1
85	1FK6044-7AF7_ ²⁾	3000	3,5	4,0
86	1FK6044-7AH72)	4500	3,0	4.8
87	1FK6061-7AF7_ 2)	3000	5,4	5,3
88	1FK6061-7AH7_ 2)	4500	4.3	6.3
89	1FK6064-7AF7_ 2)	3000	8.0	7.5
90	1FK6081-7AF71	1)	1)	1)
91	1FK6081-7AH71	1)	1)	1)
92	1FK6084-7AF71	1)	1)	1)
93	1FK6084-7AH71	1)	1)	1)

Table 8-4 Motor list 1FK6 / 1FT6

¹⁾ Data not yet known at V1.40

²⁾ FromV1.41
Only temporary arithmetic data are filed in the V1.41.

1PH7 (=1PA6) / 1PL6 / 1PH4

NOTE

1PH7xxx is the new designation of what were formerly 1PA6xxx motors. The 1PH7xxx and 1PA6xxx data therefore tally.

Input in P097	Motor order number (MLFB)	Speed	Torque T _n [Nm]	Current In [A]
1	1PA6101-4 F	1750	24	9.0
2	1PA6103-4_D	1150	36	9.6
3	1PA6103-4_F	1750	34	12.7
4	1PA6103-4_G	2300	31	15.4
5	1PA6105-4_F	1750	44	16.2
6	1PA6107-4_D	1150	60	16.0
7	1PA6107-4_F	1750	57	20.1
8	1PA6131-4_F	1750	71	23.7
9	1PA6133-4_D	1150	112	27.5
10	1PA6133-4_F	1750	96	33.1
11	1PA6133-4_G	2300	93	42.3
12	1PA6135-4_F	1750	117	40.0
13	1PA6137-4_D	1150	162	40.6
14	1PA6137-4_F	1750	136	53.0
15	1PA6137-4_G	2300	127	53.9
16	1PA6163-4_B	400	227	28.2
17	1PA6163-4_D	1150	208	52.1
18	1PA6163-4_F	1750	185	69.0
19	1PA6163-4_G	2300	158	78.5
20	1PA6163-4_B	400	310	35.6
21	1PA6167-4_D	1150	257	66.4
22	1PA6167-4_F	1750	224	75.2
23	MPA6184-4_B	400	390	51.0
24	1PA6184-4_D	1150	366	89.0
25	1PA6184-4_F	1750	325	122.0
26	1PA6184-4_L	2900	265	158.0
27	1PA6186-4_B	400	506	68.0
28	1PA6186-4_D	1150	485	116.0
29	1PA6186-4_F	1750	465	168.0
30	1PA6186-4_L	2900	333	205.0
31	1PA6224-4_B	400	725	89.0
32	1PA6224-4_D	1150	670	162.0
33	1PA6224-4_F	1750	605	205.0
34	1PA6224-4_L	2900	490	275.0
35	1PA6226-4_B	400	935	116.0
36	1PA6226-4_D	1150	870	200.0

Input in	Motor order	Speed	Torque	Current
P097	number (MLFB)	n _n [1/min]	T _n [Nm]	I _n [A]
37	1PA6226-4_F	1750	737	255.0
38	1PA6226-4_L	2900	610	35.0
39	1PA6228-4_B	400	1145	13.8
40	1PA6228-4_D	1150	1070	24.0
41	1PA6228-4_F	1750	945	35.0
42	1PA6228-4_L	2900	710	40.5
43	1PL6184-4_B	400	585	6.9
44	1PL6184-4_D	1150	540	12.1
45	1PL6184-4_F	1750	486	16.6
46	1PL6184-4_L	2900	372	20.9
47	1PL6186-4_B	400	752	9.0
48	1PL6186-4_D	1150	706	15.8
49	1PL6186-4_F	1750	682	23.1
50	1PL6186-4_L	2900	494	28.4
51	1PL6224-4_B	400	1074	11.7
52	1PL6224-4_D	1150	997	21.8
53	1PL6224-4_F	1750	900	29.2
54	1PL6224-4_L	2900	675	36.5
55	1PL6226-4_B	400	1361	14.5
56	1PL6226-4_D	1150	1287	27.5
57	1PL6226-4_F	1750	1091	35.5
58	1PL6226-4_L	2900	889	48.5
59	1PL6228-4_B	400	1719	18.1
60	1PL6228-4_D	1150	1578	33.4
61	1PL6228-4_F	1750	1448	47.3
62	1PL6228-4_L	2900	988	53.4
63	1PH4103-4HF	1500	48	20.2
64	1PH4105-4HF	1500	70	27.3
65	1PH4107-4HF	1500	89	34.9
66	1PH4133-4HF	1500	95	34.1
67	1PH4135-4HF	1500	140	51.2
68	1PH4137-4HF	1500	172	60.5
69	1PH4163-4HF	1500	236	86.3
70	1PH4167-4HF	1500	293	103.3
71	1PH4168-4HF	1500	331	113.0
72	1PH7107-2_G	2000	50	24.8

Table 8-5 Motor list 1PH7(=1PA6) / 1PL6 / 1PH4

8.7 Motor identification

From Version V1.30 onwards, automatic motor identification is available. In the case of Siemens motors (P095 = 1 or 2) the motor type is first selected in P096 or P097. In the case of non-Siemens motors (P095 = 3 or 4), the rating plate data and number of pole pairs have to be entered, and then automatic paramterizing is called with P115 = 1.

After exit from the "drive initial start-up" status with P060 = 1, P115 = 2 is set and hence motor identification is selected. The converter must now be switched in within 30 s so that measuring can start. The alarm A078 is set during the 30 s.

CAUTION



The motor shaft can move slightly during the measurement operation. The motor cables are live. Voltages are present at the converter output terminals and hence also at the motor terminals; they are therefore hazardous to touch.

WARNING



It must be ensured that no danger for persons and equipment can occur by energizing the power and the unit.

If measurement is not started within 30 s or if it is interrupted by an OFF command, error F114 is set. The converter status during measurement is "Motid-Still" (r001 = 18). Measurement is ended automatically, and the converter reverts to the status "Ready for start-up" (r001 = 009).

In current-controlled mode (P290 = 0), automatic motor indentification should **always** be performed during initial start-up.

8.8 Complete parameterization

To make full use of the complete functionality of the inverter/converter, parameterization must be carried out in accordance with the "Compendium". You will find the relevant instructions, function diagrams and complete lists of parameters, binectors and connectors in the Compendium.

Language Compendium order number	
German	6SE7080-0QX50
English	6SE7087-6QX50
French	6SE7087-7QX50
Spanish	6SE7087-8QX50
Italian	6SE7087-2QX50

10.98 Maintenance

9 Maintenance

WARNING



SIMOVERT MASTERDRIVES units are operated at high voltages. All work carried out on or with the equipment must conform to all the national electrical codes (VBG 4 in Germany).

Maintenance and service work may only be executed by qualified personnel.

Only spare parts authorized by the manufacturer may be used. The prescribed maintenance intervals and also the instructions for repair and replacement must be complied with.

Hazardous voltages are still present in the drive units up to 5 minutes after the converter has been powered down due to the DC link capacitors. Thus, the unit or the DC link terminals must not be worked on until at least after this delay time.

The power terminals and control terminals can still be at hazardous voltage levels even when the motor is stationary.

If it is absolutely necessary that the drive converter be worked on when powered-up:

- · Never touch any live parts.
- Only use the appropriate measuring and test equipment and protective clothing.
- Always stand on an ungrounded, isolated and ESD-compatible pad.

If these warnings are not observed, this can result in death, severe bodily injury or significant material damage. Maintenance 10.98

9.1 Replacing the fan

The fan is designed for an operating time of $L_{10} \ge 35\,000$ hours at an ambient temperature of $T_u = 40\,^{\circ}\text{C}$. It should be replaced in good time to maintain the availability of the unit.

The units have a fan which operates as soon as the unit is connected to the voltage supply.

Construction types A to C

The fan is located on the bottom of the unit.

Replace the fan as follows:

- ♦ Undo the two M4x49 Torx screws
- Pull out the protective cover together with the fan from underneath
- ♦ Withdraw fan connector X20
- Install the fan in reverse sequence.




Fig. 9-1 Cover and fan for housing size A to C

10.98 Maintenance

Construction type D

The fan is screwed onto a bracket and is located at the bottom section of the unit.

Replace the fan as follows:

- Withdraw fan connector X20.
- ♦ Unscrew the two M5x16 Torx screws at the bottom of the unit.
- Pull the bracket out of the unit from underneath.
- Unscrew the M4 fan screws.
- Install the fan in reverse sequence.




Fig. 9-2 Fan with bracket for housing size D

Replacing the fan fuse (type D)

The fuses are located in the upper section of the unit in a fuse holder. You have to open the fuse holder to replace the fuses.




Fig. 9-3 Fuse holder for housing size D

Maintenance 10.98

9.2 Replacing the PMU

Replacing the PMU

- Turn the snaps on the front cover by 90 °
- Open up the front cover
- Withdraw connector X108 on the CU (Control Unit)
- Remove ribbon cable from the guide hooks
- Carefully press the snap catches upwards on the inner side of the front cover using a screwdriver
- ◆ Tilt the PMU and remove it
- Install new PMU in reverse sequence.




Fig. 9-4 Replacing the PMU

10.98 Maintenance

9.3 Replacing the DC link fuses

Construction types A and B

The DC link fuses are not accessible on types A and B. They must therefore only be replaced by the service personnel.

Construction types C and D

The position of the fuses can be seen from the relevant block diagram.

Procedure:

- ♦ Remove side plate
- Replace the defective fuses:
 - Fuses F1 and F2 on type C
 - Fuses F1, F3 or F1 to F4 on type D




Fig. 9-5 Position of the DC link fuses

Replacement fuses

Inverter MLFB	Fuse	Part reference	Fuse order number
6SE7026-0TD51 6SE7027-2TD51	80 A, 700 V	F1, F2, F3, F4	6SY7000-0AC73
6SE7022-6TC51 6SE7023-4TC51	100 A, 700 V	F1, F2	6SY7000-0AC72
6SE7023-8TD51 6SE7024-7TD51	100 A, 700 V	F1, F3	6SY7000-0AC72

MAN Westical Still Still

10.98 Forming

10 Forming

If a unit has been non-operational for more than one year, the DC link capacitors have to be newly formed. If this is not carried out, the unit can be damaged when the line voltage is powered up.

If the unit was started-up within one year after having been manufactured, the DC link capacitors do not have to be re-formed. The date of manufacture of the unit can be read from the serial number.

How the serial number is made up

(Example: A-J60147512345)

Digit	Example	Meaning
1 and 2	A-	Place of manufacture
3	J	1997
	K	1998
	L	1999
	M	2000
4	1 to 9	January to September
	0	October
	N	November
	D	December
5 to 14		Not relevant for forming

The following applies for the above example:

Manufacture took place in June 1997.

During forming, the DC link of the unit is connected up via a rectifier, a smoothing capacitor and a resistor.

As a result, the DC link capacitors receive a defined voltage and a limited current, and the internal conditions necessary for the function of the DC link capacitors are restored.




Fig. 10-1 Forming circuit

Forming 10.98

Components for the forming circuit (suggestion)

♦ Rectifier (A): SKD 62/16

• Resistor (R): 470 Ω, 100 W

♦ Capacitor (C): 22 nF, 1600 V

Procedure

 Before you form the DC link capacitors, all DC link connections must be disconnected.

- The converter incoming power supply must be switched off.
- ◆ Connect the required components in accordance with the circuit example.
- Energize the forming circuit. The duration of forming depends on the idle time of the inverter.




Fig. 10-2 Forming time as a function of converter idle time

10.99 Technical Data

11 Technical Data

EC Low-voltage directive 73/23/EEC and RL93/68/EEC	EN 50178
EC EMC directive 89/336/EEC	EN 61800-3
EC Machinery safety directive 89/392/EEC	EN60204-1
Approvals	UL: E 145 153 CSA: LR 21 927
Type of cooling	Air cooling with built-in fan
Permissible ambient and cooling- medium temperature	
during operation	0° C to +40° C (32° F to 104° F) (up to 50° C see Fig. "Derating curves")
during storage	-25° C to +70° C (-13° F to 158° F)
during transport	-25° C to +70° C (-13° F to 158° F)
Installation altitude	≤ 1000 m above sea level (100 % load capability) > 1000 m to 4000 m above sea level (for load capability: see Fig. "Derating curves")
Permissible humidity rating	Relative air humidity ≤ 95 % during transport and storage ≤ 85 % during operation (moisture condensation not permissible)
Environmental conditions acc. to DIN IEC 721-3-3	climate: 3K3 chemical active substances: 3C1
Pollution degree	Pollution degree 2 to IEC 664-1 (DIN VDE 0110. Part 1). Moisture condensation during operation is not permissible
Overvoltage category	Category III to IEC 664-1 (DIN VDE 0110. Part 2)
Degree of protection	IP20 EN 60529
Protection class	Class 1 to IEC 536 (DIN VDE 0106. Part 1)
Shock protection	to EN 60204-1 and to DIN VDE 0106. Part 100 (VBG4)
Radio interference suppression	to EN 61800-3
Standard	No radio interference suppression
Options	Radio interference suppression filter for class A1 acc. to EN 55011
Interference immunity	Industrial to EN 61800-3
Paint finish	For interior installation
Mechanical specifications Vibrations During stationary use: Constant amplitude	to DIN IEC 68-2-6
- of deflection	0.075 mm in the frequency range 10 Hz to 58 Hz
- of acceleration	9.8 m/s² in the frequency range > 58 Hz to 500 Hz
During transport	
- Deflection	3.5 mm in frequency range 5 Hz to 9 Hz
- Acceleration	9.8 m/s ² in frequency range > 9 Hz to 500 Hz
Shocks	to DIN IEC 68-2-27 / 08.89
•	30 g. 16 ms half-sine shock
Drop and topple	to DIN IEC 68-2-31 / 04.84 on a surface and on a corner
	on a sunace and on a conner

Table 11-1 General data

Technical Data 10.99

Designation		Value					
Order number 6SE70)	16-1TA51	18-0TA51	21-0TA51	21-3TB51	21-8TB51	22-6TC51
Rated voltage Input Output	[V]	DC 510 to 650 (-15 % / +10 %) 3 AC 0 rated input voltage x 0.64					
Rated frequency Input Output	[Hz]	0 400			*		
Rated current Input Output	[A]	7.3 6.1	9.5 8.0	12.1 10.2	15.7 13.2	20.8 17.5	30.4 25.5
DC link voltage	[V]			= rated dir	ect voltage	70	
Rated output	[kVA]	4.04.9	5.36.4	6.78.1	8.710.5	11.513.9	16.820.3
Aux. power supply	[V]	DC	24 (20 -30)	(2.0 A withou	ıt options; mo	ore with optio	ns)
Pulse frequency	[kHz]			5.0 –	10.0		
Load class II to EN60)146-1-1:						
Base load current Overload current Cycle time Overload duration		0.91 x rated output current 1.6 x rated output current 300 s 30 s					
Losses, cooling, power	er factor						
Power factor Converter cosφU		< 0.92 ind.	< 0.92 ind.	< 0.92 ind.	< 0.92 ind.	< 0.92 ind.	< 0.92 ind.
Efficiency η Pulse frequency 5 I	kHz	0.97	0.98	0.98	0.98	0.98	0.98
Dissipated losses Pulse frequency 5 I	[kW] kHz	0.15	0.17	0.21	0.23	0.30	0.43
Cooling air required	[m³/s]	0.009	0.009	0.009	0.022	0.022	0.028
Sound pressure level, dimensions, weights							
Sound pressure level [dB(A)]		60	60	60	60	60	60
Type of construction		Α	А	Α	В	В	С
Width Height Depth	[mm]	90 42 5 350	90 425 350	90 425 350	135 425 350	135 425 350	180 600 350
Weight	[kg]	8.5	8.5	8.5	12.5	12.5	21


10.99 Technical Data

Designation		Value						
Order number 6SE70		23-4TC51 23-8TD51 24-7TD51 26-0TD51 27-2TD51						
Rated voltage Input Output	[V]		DC 510 to 650 (-15 % / +10 %) 3 AC 0 rated input voltage x 0,64					
Rated frequency Input Output	[Hz]		 0 400				*	
Rated current Input Output	[A]	40.5 34.0	44.6 37.5	55.9 47.0	70.2 59.0	85.7 72.0	?	
DC link voltage	[V]		T	= rated dire	ect voltage			
Rated output	[kVA]	22.427.1	24.729.9	30.937.4	38.847.0	47.457.4		
Aux. power supply	[V]	DC	24 (20 -30)	(2.0 A withou	it options; mo	ore with optio	ns)	
Pulse frequency	[kHz]			5.0 –	10.0			
Load class II to EN60	146-1-1:							
Base load current Overload current Cycle time Overload duration		0.91 x rated output current 1.6 x rated output current 300 s 30 s						
Losses, cooling, power	er factor							
Power factor Converter cosφU		< 0.92 ind.	< 0.92 ind.	< 0.92 ind.	< 0.92 ind.	< 0.92 ind.		
Efficiency η Pulse frequency 5 k	Hz	0.98	0.98	0.98	0.98	0.98		
Dissipated losses Pulse frequency 5 k	[kW] :Hz	0.59	0.70	0.87	1.02	1.27		
Cooling air required [m³/s]		0.028	0.054	0.054	0.054	0.054		
Sound pressure level, dimensions, weights								
Sound pressure level	[dB(A)]	60	65	65	65	65		
Type of construction		C	D	D	D	D		
Width Height Depth	[mm]	180 600 350	270 600 350	270 600 350	270 600 350	270 600 350		
Weight	[kg]	21	32	32	32	32		

Table 11-2 Technical data


NOTE


Complete fulfillment of the degree of protection IP20 in accordance with EN 60529 is dependent on how many incoming and outgoing control cables cover the opening area on the lower section of the unit. If degree of protection IP20 also has to be met in operation, the opening may have to be subsequently reduced.



Technical Data 10.99

Derating curves





<1>

Permissible rated current in %

100

90

80

70

60

2000


The more favourable derating curve is only applicable for units of sizes B to D with a rated input voltage of 510 V - 540 V

Altitude [m]	Derating factor K ₁
1000	1.0
2000	0.9
3000	0.845
4000	0.8

Installation altitude above sea level in m

3000

4000



1000

Fig. 11-1 Derating	curves	
--------------------	--------	--

Temp [°C]	Derating factor K ₂
50	0.76
45	0.879
40	1.0
35	1.125 *
30	1.25 *
25	1.375 *

See following note 10.99 Technical Data

The derating of the permissible rated current for installation altitudes of over 1000 m and at ambient temperatures below 40 °C is calculated as follows:

Total derating = Derating_{altitude} x Derating_{ambient} temperature $K = K_1 \times K_2$

NOTE

It must be borne in mind that total derating must not be greater than 1!

Example: Altitude: 3000 m $K_1 = 0.845$

Ambient temperature: 35 °C $K_2 = 1.125$ \Rightarrow Total derating = 0.845 x 1.125 = 0.95

Rating plate




Fig. 11-2 Rating plate

Date of manufacture

The date of manufacture can be derived as follows:

Character	Year of manufacture:	Character	Month of manufacture
J	1997	1 to 9	January to September
K	1998	0	October
L	1999	N	November
М	2000	D	December

Table 11-3 Assignment of characters to the month and year of manufacture

Technical Data 10.99

Option codes

Option	Meaning	Option	Meaning
	SBP: Pulse encoder evaluation		CBP2: PROFIBUS (sync freq possible)
C11 C13 C14 C15	Slot A Slot C Slot D Slot E	G91 G93 G95 G97	Slot A Slot C Slot E Slot G
C16 C17	Slot F Slot G	Gar	The CBP2 module takes the place of the CB.
C23	SBR1: Resolver evaluation without pulse encoder simulation Slot C SBR2: Resolver evaluation with	G21 G23 G24	CBC: CAN bus Slot A Slot C Slot D
C33	pulse encoder simulation Slot C SBM: Absolute-value encoder evaluation	G25 G26 G27	Slot E Slot F Slot G EB1: Expansion Board 1
C51 C53 C54 C55 C56 C57	Slot A Slot C Slot D Slot E Slot F Slot G	G61 G63 G64 G65 G66 G67	Slot A Slot C Slot D Slot E Slot F Slot G
	SLB: SIMOLINK		EB2: Expansion Board 2
G41 G43 G44 G45 G46 G47	Slot A Slot C Slot D Slot E Slot F Slot G	G71 G73 G74 G75 G76 G77	Slot A Slot C Slot D Slot E Slot F Slot G
G11 G13	CBP: PROFIBUS Slot A Slot C	K11	LBA backplane adapter integrated in the electronics box. ADB adapter board
G14 G15 G16 G17	Slot C Slot D Slot E Slot F Slot G	K01 K02	Mounting position 2 (Slot D, E) Mounting position 3 (Slot F, G)

Table 11-4 Meaning of the option codes

12 Faults and Alarms

12.1 Faults

General information regarding faults

For each fault, the following information is available:

Parameter r947 Fault number

been selected, see P373).

r949 Fault value r951 Fault list P952 Number of faults

r782 Fault time

If a fault message is not reset before the electronic supply voltage is switched off, then the fault message will be present again when the electronic supply is switched on again. The unit cannot be operated without resetting the fault message. (Exception: Automatic restart has

Number / Fault	Cause	Counter-measure
F001	The monitoring time of the main contactor	- Check main contactor checkback
	checkback (P600) has expired.	- Clear main contactor checkback (P591.B =
Main contactor	X.	0)
checkback		Increase monitoring time (P600)
F002	The monitoring time of pre-charging has	- Check voltage connection (AC or DC)
	expired, i.e. the DC link voltage has not	- Compare value in P070 and unit MLFB
Pre-charging fault	reached the setpoint within 3 secs.	
F006	Due to excessive DC link voltage, shutdown	Check the line voltage (AC-AC) or the input
	has occurred (shutdown threshold approx.	direct voltage (DC-AC). Compare value with
DC link overvoltage	820 V)	P071 (Line Volts)
F008	The lower limit value of 76% of the DC link	- check the line voltage (AC-AC) or the input
	voltage has been fallen short of.	direct voltage (DC-AC). Compare value with
DC link undervoltage		P071 (Line Volts)
		- check input rectifier (AC-AC)
	~' ()	
		- check DC link
F011	Overcurrent shutdown has occurred.	- Check the converter output for short-circuit or
	The shutdown threshold has been exceeded.	earth fault
Overcurrent		
	The phase in which an overcurrent has	- Check the load for an overload condition
	occurred is indicated in a bit-coded manner in	
	the fault value (see P949).	- Check whether motor and converter are
		correctly matched
	Phase U> Bit 0 = 1> fault value = 1	
	Phase V> Bit 1 = 1> fault value = 2	- Check whether the dynamic requirements
	Phase W> Bit 2 = 1> fault value = 4	are too high
	If an overcurrent occurs simultaneously in	
	several phases, the total of the fault values of	
	the phases concerned is the resulting fault	
	value.	

Number / Fault	Cause	Counter-measure
F015	Motor is blocked/overloaded (current control),	- Reduce the load
Motor blocked	or has stalled (v/f characteristic):	- Release the brake
	Static load is too high	- Increase current limits
	The fault is not generated until after the time entered in P805.	- Increase P805 Blocking Time
	Binector B0156 is set, in status word 2 r553 Bit 28.	- Increase the response threshold for the permissible deviation P792 - Increase torque limits or torque setpoint v/f characteristic only:
	Whether the drive is blocked or not can be detected at P792 (Perm Deviation) and P794. P806 enables detection to be limited to "at standstill" (P806 = 1, only for current control) or to be completely de-activated (P806 = 2). In the case of current control, the precondition for this fault is that the torque limits (B0234) have been reached.	- Reduce rate of acceleration - Check characteristic setting.
	In the case of slave drive, detection is deactivated.	
	In the case of v/f control, the I(max) controller must be active.	
F017	SAFE OFF operating or failure of the 24 V	Jumper applied for SAFE OFF?
SAFE OFF	power supply during operation (only for Compact PLUS units)	SAFE OFF checkback connected? On Compact PLUS units: check 24 V supply
F020	The motor temperature limit value has been	- Temperature threshold adjustable in P381!
Excess temperature of motor	exceeded. r949 = 1 Motor temperature limit value	- P131 = 0 -> fault de-activated
	exceeded	- Check the motor (load, ventilation etc.)
	r949 = 2 Short-circuit in the motor temperature sensor cable or sensor defective	- The current motor temperature can be read in r009 (Motor Temperat.)
	r949 = 4 Wire break of motor temperature sensor cable or sensor defective	- Check the sensor for cable break, short-circuit
F021	Parameterized limit value of the I2t monitoring for the motor (P384.002) has been exceeded	Check: Thermal time constant of motor P383 Mot ThermT-Const or motor I2t load limit
Motor I2t		P384.002. The I2t monitoring for the motor is automatically activated if P383 >=100s (=factory setting) and P381 > 220°C is set. Monitoring can be switched off by setting a value <100s in P383.
F023	The limit value of the inverter temperature has been exceeded	- Measure the air intake and ambient temperature.
Excess temperature of inverter	7	- Observe the derating curves at theta > 50 °C (Compact PLUS) or 40 °C
		- Check whether the fan is running
		- Check that the air entry and discharge openings are not restricted
F025	UCE upper switch (Compact PLUS) / UCE Phase L1 (chassis-type unit)	- Check the converter outputs for earth fault
UCE upper switch/UCE Phase L1		- Check the switch for "Safe OFF" on Compact units
F026	UCE lower switch (Compact PLUS) / UCE Phase L2 (Compact, chassis)	- Check the converter outputs for earth fault
UCE lower switch/UCE Phase L2	LE (compact, cridolo)	- Check the switch for "Safe OFF" on Compact units

Number / Fault	Cause	Counter-measure
F027	Pulse resistance fault (only Compact PLUS) /	- Check the converter outputs for earth fault
Dulas vasiatav fault /	UCE Phase L3 (chassis)	Charletha aviitab far IICafa OFFII an Caranaat
Pulse resistor fault / UCE Phase L3		- Check the switch for "Safe OFF" on Compact units
F029	A fault has occurred in the measured value	Fault in measured value sensing
	sensing system:	
Meas. value sensing	(040 4) 0% + 11 + 11 + 11	Fault in power section (valve cannot block)
Compact PLUS only	- (r949 = 1) Offset adjustment in phase L1 not possible	Fault on CU
Compact Loc only	possible	T dall off co
	- (r949 = 2) Offset adjustment in phase L3 not possible.	5
	- (r949 = 3) Offset adjustment in phases L1 and L3 not possible.	
	- (r949=65) Autom. Adjustment of the analog inputs is not possible	10
F035	Parameterizable external fault input 1 has	- Check whether there is an external fault
External fault 1	been activated.	- Check whether the cable to the
		corresponding digital output is interrupted
		- P575 (Src No ExtFault1)
F036	Parameterizable external fault input 2 has been activated.	- Check whether there is an external fault
External fault 2		- Check whether the cable to the
		corresponding digital output is interrupted
F038	A voltage failure has occurred during a	- P576 (Src No ExtFault2) Re-enter the parameter. The number of the
FU30	parameter task.	parameter concerned is indicated in fault value
Voltage OFF during	, and a second	r949.
parameter storage		
F040 Internal fault of	Incorrect operating status	Replace the control board (CUMC) or the unit (Compact PUS).
sequence control		
F041	A fault has occurred during the storage of	Replace the control board (CUMC) or the unit
=======================================	values in the EEPROM.	(Compact PLUS)
EEPROM fault F042	The available relaulating time of the time elet	- Reduce pulse frequency
FU42	The available calculating time of the time slot has been exceeded.	- Reduce pulse frequency
Time slot overflow	nas bosh excesses.	- Calculate individual blocks in a slower
	*	sampling time
F043	The link to the internal signal processor is interrupted	- Reduce pulse frequency (perhaps caused by
DSP link	Interrupted	calculating time overflow) - If fault re-occurs, replace the board/unit
F044	A fault has occurred in the softwiring of	Fault value r949:
BICO manager fault	binectors and connectors	>1000: Fault during connector softwiring >2000: Fault during binector softwiring
		- Voltage OFF and ON
		- Factory setting and new parameterization
		- Exchange the board
		1038:Link momony is full. The link area
		1028:Link memory is full. The link area between the two processors is full. No further
		connectors can be transferred.
		- Reduction of the linked connections between
		the two processors. Interface between the two
•		processors is position control/setpoint
		conditioning i.e.softwires from and to the
		setpoint conditioning, position controller, speed controller, torque interface and current
		controller which are not necessary should be
4		dissolved to reduce the link (value 0).

Number / Fault	Cause	Counter-measure
F045	A hardware fault has occurred during access to an optional board.	- Replace CU board (Compact, chassis units)
HW fault on optional boards	·	- Replace the unit (Compact PLUS)
		- Check the connection betewen the subrack and the optional boards
		- Replace optional boards.
F046	A fault has occurred during the transfer of parameters to the DSP.	If fault re-occurs, replace the board/unit
Parameter coupling fault		.60

Number / Fault	Cause	Counter-measure
F051	- Signal amplitude of resolver or encoder is	Resolver/encoder
	below the tolerance threshold	fault value r949:
Encoder fault	- In the case of multiturn encoders (SSI/Endat)	9 = Resolver signal missing
	connection fault of the serial protocol	25 = Encoder initial position not recognized
	- In the case of multiturn encoders (SSI/Endat)	(C/D track missing from V1.32)
	connection fault of the serial protocol	- Check encoder cable (faulty / interrupted)?
		- Correct encoder type parameterized?
		- Is the correct cable used for encoder or multiturn encoder? Encoders and multiturn
		encoders need different cables!
		- Encoder faulty?
		26 = Encoder zero pulse outside the permitted
		range
		27 = No encoder zero pulse has occurred
		28 = Voltage supply Encoder fault
		- Short-circuit in encoder connection?
		- Encoder faulty?
		- Encoder incorrectly connected up?
		!!!Power off/on or in drive settings and back to
		new initialization of the starting position!!!
		29 = Encoder/ multiturn encoder signal is
		missing
		And encoder starting position not reccognized (C/D track missing to V1.31)
		- Check encoder cable (faulty/torn off)?
		- Is shield of encoder cable connected?
		- Encoder faulty?
		- Replace SBR/SBM
		- Replace unit or basic board
		- Is the correct cable being used in each case
		for the encoder/multiturn encoder? Encoders
		and multiturn encoders require different
		encoder cables!
		!!!Power off/on or in drive settings and back to
		new initialization of the starting position!!!
		Madichara (COL/FaDat)
		Multiturn (SSI/EnDat):
		Fault value r949: 30: Protocol fault CRC/Parity Check
		31: Timeout Protocol (EnDat)
		32: Neutral level fault
		33: Initialization of timeout
	• / /	- Check parameterization (P149)
		- Check encoder cable (faulty / torn off?
		- Encoder cable shield connected ?
		- Encoder faulty?
		- Replace SBR/SBM
		- Replace unit or basic board
	X	(5 5 6
		34: Address wrong (only EnDat)
		Writing or reading of parameters not
		successful, check address and MRS code (P149)
		(1 170)
_		40-48: Encoder alarms (only EnDat)
		Check voltage supply to encoder, battery
		change on battery-backed-up systems,
		encoder faulty
		,
	7	49: Alarm bit set
		Parameterization (P149), Encoder alarm
		50-59: Alarms EnDat encoder
•		Fault value + 100 decignates the
		Fault value + 100 designates the corresponding faults of the external encoder.
		corresponding radius of the external encoder.

Number / Fault	Cause	Counter-measure
F053	After changes have been made to parameters,	No remedy
Parameter fault in	a fault has occurred during the calculation of dependent parameters.	
follow-up task	dependent parameters.	
F054	A fault has occurred during initialization of the	Fault value r949:
	encoder board.	1: Board code is incorrect
Encoder board		2: TSY not compatible
initialization fault		3: SBP not compatible
		4: SBR not compatible
		5: SBM not compatible 6: SBM initialization timeout
		7: Board double
		20: TSY board double
		21: SBR board double
		23: SB board three-fold
		24: SBP board three-fold
		30: SBR board slot incorrect
		31: SBM board slot incorrect
		32: SBP board slot incorrect
		40: SBR board not present
		41: SBM board not present
		42: SBP board not present
		50: Three encoder boards
		60: internal fault
F056	Communication on the SIMOLINK ring is	- Check the fiber-optic cable ring
CIMOLINIK talamana	disturbed.	Charle whather an CLD in the sign is without
SIMOLINK telegram failure		- Check whether an SLB in the ring is without voltage
laliuic		Voltage
		- Check whether an SLB in the ring is faulty
	A . U	
		- Check P741 (SLB TlgOFF)
F058	A fault has occurred during the processing of a	No remedy
Parameter fault	parameter task.	
Parameter task		
F059	A fault has occurred in the initialization phase	The number of the inconsistent parameter is
	during the calculation of a parameter.	indicated in fault value r949. Correct this
Parameter fault after		parameter (ALL indices) and switch voltage off
factory setting/init.	*. \	and on again. Several parameters may be
F060	Is set if parameter P070 is at zero when	affected, i.e. repeat process. Enter correct MLFB after acknowledging the
1 000	INITIAL LOADING is exited.	fault (power section, initial loading)
MLFB is missing during	X	,
initial loading		
F061	A parameter which has been entered during	The number of the inconsistent parameter is
Incorrect	drive setting is in the non-permissible range.	indicated in fault value r949 (e.g. motor
Incorrect parameterization		enocder = pulse encoder in the case of brushless DC motors) -> correct this
parametenzation	/)	parameter.
F063	The synchronization or positioning technology	- Deactivate synchronization or positioning
	functions have been activated without an	- Enter the PIN (U2977)
PIN is missing	authorization being present (PIN)	

Number / Fault	Cause	Counter-measure
F065	No telegram has been received at an SCom	Fault value r949:
	interface (SCom/USS protocol) within the	
SCom telegram failure	telegram failure time.	1 = Interface 1 (SCom1)
		2 = Interface 2 (SCom2)
		Check the connection of PMU -X300 or X103
		27,28 (Compact, chassis unit)
		21,20 (compact, chassis a.m.)
		Check the connection of X103 or X100 / 35,36
		(Compact PLUS unit)
		Check "SCom/SCB TlgOff" P704.01 (SCom1)
F070	A fault has occurred during initialization of the	or P704.02 (SCom2) Fault value r949:
1070	SCB board.	r ault value 1949.
SCB initialization fault	GGD Board.	1: Board code incorrect
		2: SCB board not compatible
		5: Error in configuration data
		6: Initialization timeout
		7: SCB board double
F070	A fault has assumed during initialization of the	10: Channel error Fault value 1949:
F072	A fault has occurred during initialization of the EB board.	2: 1st EB1 not compatible
EB initialization fault	EB board.	3: 2nd EB1 not compatible
EB milianzation radit		4: 1st EB2 not compatible
		5: 2nd EB2 not compatible
		21: Three EB1 boards
		22: Three EB2 boards
		110 E II 1 1 ED1
		110: Fault on 1st EB1 120: Fault on 2nd EB1
		210: Fault on 1st EB2
		220: Fault on 2nd EB2
F073	4 mA at analog input 1, slave 1 fallen short of	Check the connection of the signal source to
		the SCI1 (slave 1) -X428: 4, 5.
AnInp1SL1		
not Compact PLUS F074	A ma A standard in mut 2 place A fallon about of	Charletha aggregation of the simulation to
F0/4	4 mA at analog input 2, slave 1 fallen short of	Check the connection of the signal source to the SCI1 (slave 1) -X428: 7, 8.
AnInp2 SL1		the SCIT (slave 1) -7,420. 1, 0.
,		
not Compact PLUS	~'()'	
F075	4 mA at analog input 3, slave 1 fallen short of	Check the connection of the signal source to
	*. . .	the SCI1 (slave 1) -X428: 10, 11.
AnInp3 SL1		
not Compact PLUS		
F076	4 mA at analog input 1, slave 2 fallen short of	Check the connection of the signal source to
1010	This talk analog input 1, slave 2 faller effect of	the SCI1 (slave 2) -X428: 4, 5.
AnInp1 SL2		
not Compact PLUS		
F077	4 mA at analog input 2, slave 2 fallen short of	Check the connection of the signal source to
AnInp2 SL2		the SCI1 (slave 2) -X428: 7, 8.
Amilyz SLZ		
not Compact PLUS		
F078	4 mA at analog input 3, slave 2 fallen short of	Check the connection of the signal source to
		the SCI1 (slave 2) -X428: 10, 11.
AnInp3 SL2		
not Compact PLUS		

Number / Fault	Cause	Counter-measure
F079	No telegram has been received by the SCB	- Check the connections of the SCB1(2).
	(USS, peer-to-peer, SCI) within the telegram	
SCB telegram failure	failure time.	- Check P704.03"SCom/SCB Tlg OFF"
not Compact PLUS		- Replce SCB1(2)
		- Replace CU (-A10)
F080	Fault during initialization of the board at the	Fault value r949:
	DPR interface	1: Board code incorrect
TB/CB initialization		2: TB/CB board not compatible
fault		3: CB board not compatible
		5: Error in configuration data
		6: Initialization timeout
		7: TB/CB board double
		10: Channel error
		Check the T300/CB board for correct
		contacting, check the PSU power supply,
		check the CU / CB / T boards and check the
		CB initialization parameters:
		- P918.01 CB Bus Address,
F081	Lleartheat sounter of the antional heard is no	- P711.01 to P721.01 CB parameters 1 to 11
F061	Heartbeat-counter of the optional board is no longer being processed	Fault value r949: 0: TB/CB neatbeat-counter
OptBrdHeartbeat-	longer being processed	1: SCB heartbeat-counter
Counter		2: Additional CB heartbeat-counter
		- Acknowledge the fault (whereby automatic
		reset is carried out)
	X	- If the fault re-occurs, replace the board
		concerned (see fault value)
		- Replace ADB - Check the connection between the subrack
		and the optional boards (LBA) and replace, if
		necessary
F082	No new process data have been received by	Fault value r949:
	the TB or the CB within the telegram failure	1 = TB/CB
TB/CB telegram failure	time.	2 = additional CB
		- Check the connection to TB/CB
		- Check P722 (CB/TB TlgOFF)
		- Replace CB or TB
F085	A fault has occurred during initialization of the	Fault value r949:
	CB board.	1: Board code incorrect
Add. CB initialization		2: TB/CB board not compatible
fault		3: CB board not compatible
		5: Error in configuration data
		6: Initialization timeout 7: TB/CB board double
		10: Channel error
		To. Original citor
	74	Check the T300 / CB board for correct
		contacting and check the CB initialization
		parameters:
		- P918.02 CB Bus Address,
F007	A fault base assumed that the state of the	- P711.02 to P721.02 CB Parameters 1 to 11
F087	A fault has occurred during initialization of the SLB board.	- Replace CU
SIMOLINK initialization	OLD Board.	- Replace SLB
fault		•

Number / Fault	Cause	Counter-measure
F099	Recording of the friction characteristic was	Fault value r949 gives the cause (bit coded):
Friction characteristic	interrupted or not done at all.	Bit Meaning Value displayed
record		0 Pos. speed limit
		1 Neg. speed limit 2
		2 Releases missing: 4 direction of rotation, inverter, controller
		3 Speed controller connecting 8
		4 Interrupt through cancellation of the 16 record command
		5 Illegal dataset changover 32
		6 Time exceeded 64 7 Measuring error 128
F109	The rotor resistance determined during	7 Weasuring error 126
Mld R(L)	measurement of the direct current deviates too greatly.	
F111	A fault has occurred during the Mot Id.	
MIT DOD	•	
Mld DSP F112	A fault has occurred during measurement of	
	the motor inductances or leakages.	
Mid X(L) F114	The converter has automatically stopped the	Re-start with P115 function selection = 2
	automatic measurement due to the time limit	"Motor identification at standstill". The ON
Mld OFF	up to power-up having been exceeded or due to an OFF command during the measurement,	command must be given within 20 sec. after the alarm message A078 = standstill
	and has reset the function selection in P115.	measurement has appeared.
		Cancel the OFF command and re-start
	X	measurement.
F116	See TB documentation	See TB documentation
Technology board fault		
not Compact PLUS		
F117	See TB documentation	See TB documentation
Technology board fault		
F118	See TB documentation	See TB documentation
Technology board fault		
reciliology board rault		
not Compact PLUS	Our TD description	One TD de compartation
F119	See TB documentation	See TB documentation
Technology board fault		
not Compact PLUS		
F120	See TB documentation	See TB documentation
Technology board fault		
6,5		
not Compact PLUS F121	Soo TP degumentation	See TB documentation
	See TB documentation	See 1D documentation
Technology board fault		
not Compact PLUS		
F122	See TB documentation	See TB documentation
Technology board fault		
not Compact PLUS F123	See TB documentation	See TB documentation
	1	II.
Technology board fault		

Number / Fault	Cause	Counter-measure
F124	See TB documentation	See TB documentation
Technology board fault		
not Compact PLUS	See TB documentation	See TB documentation
F125	See 1B documentation	See 1B documentation
Technology board fault		
not Compact PLUS		· ·
F126	See TB documentation	See TB documentation
Technology board fault		
not Compact PLUS		
F127	See TB documentation	See TB documentation
Technology board fault		
not Compact PLUS		
F128	See TB documentation	See TB documentation
Technology board fault		
		. ()
not Compact PLUS	See TB documentation	So TP designantation
F129	See 1B documentation	See TB documentation
Technology board fault		
not Compact PLUS	X	
F130	See TB documentation	See TB documentation
Technology board fault		
not Compact PLUS		
F131	See TB documentation	See TB documentation
Technology board fault		
not Compact PLUS		
F132	See TB documentation	See TB documentation
Technology board fault		
not Compact PLUS	Coo TD do Ana	Con TD documentation
F133	See TB documentation	See TB documentation
Technology board fault		
not Compost DLUC		
not Compact PLUS F134	See TB documentation	See TB documentation
Technology board fault	7.	
not Compact PLUS		
F135	See TB documentation	See TB documentation
Technology board fault		
not Compact PLUS		
F136	See TB documentation	See TB documentation
Technology board fault		
not Compact PLUS		
not Compact FLOS		

Number / Fault	Cause	Counter-measure
F137	See TB documentation	See TB documentation
Technology board fault		
not Compact PLUS		
F138	See TB documentation	See TB documentation
Technology board fault		
not Compact PLUS		•
F139	See TB documentation	See TB documentation
Technology board fault		
not Compact PLUS		
F140	See TB documentation	See TB documentation
Technology board fault		
not Compact PLUS		
F141	See TB documentation	See TB documentation
		*
Technology board fault		
not Compact PLUS		_ ·/ F
F142	See TB documentation	See TB documentation
Technology board fault		
not Compact PLUS		
F143	See TB documentation	See TB documentation
	Coo 12 documentation	Joo 12 documentanen
Technology board fault		
not Compact PLUS		
F144	See TB documentation	See TB documentation
Technology board fault		
not Compact PLUS		
F145	See TB documentation	See TB documentation
Technology board fault	~ 0	
not Compact PLUS		
F146	See TB documentation	See TB documentation
Technology board fault		
not Compact PLUS		
F147	See TB documentation	See TB documentation
Technology board fault		
not Compact PLUS	/)	
F148	An active signal is present at binector U061	Examine cause of fault, see function diagram
	(1).	710
Fault 1		
Function blocks	An active signal is present at himseter LICCO	Everying course of fault, and function diagrams
F149	An active signal is present at binector U062 (1).	Examine cause of fault, see function diagram 710
Fault 2	(.).	
Function blocks		
F150	An active signal (1) is present at binector	Examine cause of fault, see function diagram
Fault 3	U063.	710
Function blocks		
		,

Number / Fault	Cause	Counter-measure
F151	An active signal is present at binector U064 (1).	Examine cause of fault, see function diagram 710
Fault 4		
Function blocks		
F244	Fault in the internal parameter linking	Release comparison of gating unit software and operating software regarding the transfer
ParaLink int.		parameters.
Compact PLUS only		Replace CU (-A10)
F255	A fault has occurred in the EEPROM.	Switch off the unit and switch it on again. If the
		fault re-occurs, replace the CU.
Fault in EEPROM		

Table 12-1 Fault numbers, causes and their counter-measures

12.2 Alarms

The alarm message is periodically displayed on the PMU by A = alarm/alarm message and a 3-digit number. An alarm cannot be acknowledged. It is automatically deleted once the cause has been eliminated. Several alarms can be present. The alarms are then displayed one after the other.

When the converter is operated with the OP1S operator control panel, the alarm is indicated in the lowest operating display line. The red LED additionally flashes (refer to the OP1S operating instructions).

Number / Alarm	Cause	Counter-measure
A001	The computing time work load is too high	- Reduce pulse frequency
Time slot overflow		- Calculate individual function blocks in slower
		time slots (parameter U950 ff.)
A002	Start of the SIMOLINK ring is not functioning.	- Check the fiber-optic cable ring for
		interruptions
SIMOLINK start alarm		
		- Check whether there is an SLB without
		voltage in the ring
		- Check whether there is a faulty SLB in the
		ring
A003	Although synchronization has been activated,	SIMOLINK (SLB):
71000	the drive is not synchronous.	- Check r748 i002 and i003 = counters for
Drive not synchronous	Possible causes are:	CRC faults and timeout faults
	- Poor communication connection (frequent	- Check the fiber-optic cable connection
	telegram failures)	- Check P751 on the dispatcher (connector
	- Slow bus cycle times (in the case of high bus	260 must be softwired); Check P753 on the
	cycle times or synchronization of slow time	transceiver (corresponding SIMOLINK
	slots, synchronizing can last for 1-2 minutes in	connector K70xx must be softwired).
	the worst case).	
	- Incorrect wiring of the time counter (only if	
4005	P754 > P746 /T0)	N
A005	The closed-loop electronic system of MASTERDRIVES MC consists of two	None
Couple full	microprocessors. Only a limited number of	
Couple Iuli	couple channels are provided for transferring	
	data between the two processors.	
	The alarm displays that all couple channels	
	between the two processors are busy. An	
	attempt has, however, been made to	
	interconnect another connector requireing a	
	couple channel,	
A014	The DC link voltage is not equal to 0 when the	- Set P372 to 0.
	simulation mode is selected (P372 = 1).	
Simulation active alarm		- Reduce DC link voltage (disconnect the
1015		converter from the supply)
A015	Parameterizable external alarm input 1 has	Check
External clarm 1	been activated.	whether the cable to the corresponding
External alarm 1		- whether the cable to the corresponding digital input has been interrupted.
		digital input has been interrupted.
		- parameter P588 Src No Ext Warn1
A016	Parameterizable external alarm input 2 has	Check
1.5.5	been activated.	J. 133
External alarm 2		- whether the cable to the corresponding
		digital input has been interrupted.
•		· '
		- parameter P589 Src No Ext Warn2
A017	SAFE OFF is detected in the READY states.	See F017 for causes/counter-measures.
SAFE OFF alarm		
active		<u> </u>

Number / Alarm	Cause	Counter-measure
A018	Signal amplitude resolver/encoder in critical	See F051 for causes/counter-measures.
Encoder adjustment	range Resolver/encoder in the critical range.	As a general rule, it is necessary to initialize
		the starting position again => power OFF/ON or switch to the drive settings and back again!!!
		If alarm A18 occurs in the "Ready" status (r001
		= 009) while an encoder is in use, the amplitude of the CD track signal is too small,
		or the connection to CD_Track may be
		interrupted, or an encoder without CD-Track is in use.
		In the case of an encoder without CD track, the P130 must be correctly set.
A019	Connection fault of the serial protocol on multiturn encoders (SSI/Endat)	Serial protocol is defective on multiturn encoders. See F051 for causes/counter-
Encoder data serial protocol	multum encoders (00% Endat)	measures.
		As a general rule, it is necessary to initialize
		the starting position again => power OFF/ON or switch to the drive settings and back
A020	The amplitude of an external encoder lies in	again!!! Cause/remedies see F051
A020	the critical range.	
Encoder adjustment, external encoder		As a general rule, it is necessary to initialize the starting position again => power OFF/ON
oxiomal onedati		or switch to the drive settings and back
A021	A fault has occurred during processing of the	Faulty serial protocol in the case of an external
Encoder data of	serial protocol to an external code rotary encoder (SSI- or Endat-Multiturn).	multiturn encoder. Cause/remedies see F051
external multiturn encoder faulty		As a general rule, it is necessary to initialize the starting position again => power OFF/ON
		or switch to the drive settings and back again!!
A022	The threshold for tripping an alarm has been exceeded.	- Measure intake air and ambient temperature.
Inverter temperature		- Observe derating curves at theta > 50°C (Compact PLUS) or 40°C
		- Check whether the fan is operating
		- Check whether the air entry and discharge
A023	The parameterizable threshold (P380) for	openings are restricted. Check the motor (load, ventilation, etc.). Read
	tripping an alarm has been exceeded.	off the current temperature in r009 Motor
Motor temperature A025	If the current load state is maintained, a	Temperat Reduce converter load
	thermal overload of the converter occurs.	
12t converter	The converter will lower the max. current limit (P129).	- Check r010 (Drive Utiliz)
A029	The parameterized limit value for the I2t monitoring of the motor has been exceeded.	Motor load cycle is exceeded!
I2t motor		Check the parameters:
		P382 Motor Cooling P383 Mot Tmp T1
		P384 Mot Load Limits
A033	The positive or negative maximum speed has been exceeded.	- Increase relevant maximum speed
Overspeed		- Reduce regenerative load (see FD 480)

Number / Alarm	Cause	Counter-measure
A034	Bit 8 in r552 status word 1 of the setpoint	Check
6	channel. The difference between frequency	
Setpoint/actual value	setpoint/actual value is greater than the	- whether an excessive torque requirement is
deviation	parameterized value and the control	present
	monitoring time has elapsed.	- whether the motor has been dimensioned too
		small.
		Siriali.
		Increase values P792 Perm Deviation Frg/
		set/actual DevSpeed and P794 Deviation Time
A036	The brake checkback indicates the "Brake still	Check brake checkback (see FD 470)
	closed" state.	
Brake checkback		
"Brake still closed"		
A037	The brake checkback indicates the "Brake still	Check brake checkback (see FD 470)
Dualsa ahaalshaals	open" state.	, * ()
Brake checkback		
"Brake still open" A042	Motor is stalled or blocked.	Check
AU42	Wotor is stalled or blocked.	Crieck
Motor stall/block	The alarm cannot be influenced by P805	- whether the drive is blocked
motor otally blook	"PullOut/BlckTime", but by P794 "Deviation	Wilder of the different of the blocked
	Time"	- Whether the drive has stalled
A049	At serial I/O (SCB1 with SCI1/2), no slave is	P690 SSCI Analn Conf
	connected or fiber-optic cable is interrupted or	
No slave	slaves are without voltage.	- Check slave.
not Compact PLUS		- Check cable.
A050	At ser. I/O the slaves required according to a	Check parameter P693 (analog outputs), P698
Clave in an area	parameterized configuration are not present	(digital outputs). Check connectors
Slave incorrect	(slave number or slave type): Analog inputs or outputs or digital inputs or outputs have been	
not Compact PLUS	parameterized which are not physically	and binectors B4100B4115, B4120B4135, B4200B4215, B4220B4235 (digital inputs)
not Compact FLOS	present.	for connecting.
A051	In a peer-to-peer connection a baud rate has	Adjust the baud rate in conjunction with the
AUUT	been selected which is too high or too	SCB boards P701 SCom/SCB Baud Rate
Peer baud rate	different.	
not Compact PLUS		
A052	In a peer-to-peer connection, a PcD length has	Reduce number of words P703 SCom/SCB
	been set which is too high (>5).	PcD #
Peer PcD L		
. 0		
not Compact PLUS	In a grande grand and street the grand to the	Advertibe weed by oth for the condition and
A053	In a peer-to-peer connection, the pcD length of	
Door I no f	transmitter and receiver do not match.	receiver P703 SCom/SCB PcD #
Peer Lng f.		F 703 3C0III/3CB FCD #
not Compact PLUS	X	
A057	Occurs when a TB is logged on and present,	Replace TB configuration (software)
	but parameter tasks from the PMU, SCom1 or	
TB Param	SCom2 have not been answered by the TB	
	within 6 seconds.	
not Compact PLUS		
A061	An active signal is present at binector U065	Check cause of alarm (see FD 710)
	(1).	
Alarm 1		
Function blocks)	0
A062	An active signal is present at binector U066	Check cause of alarm (see FD 710)
Alama O	(1).	
Alarm 2		
Function blocks	An active signal is massed at 15 and at 1997	Obselvenue of plants (FD 740)
A063	An active signal is present at binector U067	Check cause of alarm (see FD 710)
Alarm 3	(1).	
Function blocks		
T GLIGHOLL DIOCKS		<u> </u>

measurement or of rotor resistance deviate significantly. deviate from the average values, they a automatically not taken into account for calculation (for RI) or the value of the automatic parameterization remains (for It is only necessary to check the results their plausibility in the case of drives wirequirements on torque or speed accur		Counter-measure	Cause	Number / Alarm
Automatic initiation of the friction characteristic has been selected, but the drive has not yet been switched on. Note: If the ON command is not given within 30 seconds, the automatic initiation of the friction characteristic has been interrupted (OFF command or fault). A073 Automatic initiation of the friction characteristic has been interrupted (OFF command or fault). Note: If the drive is not switched on again within 5 minutes, the automatic initiation of the friction characteristic is stopped (Pol99). A074 Incomplete initiation of friction characteristic. A stere is a lack of enables or due to limitations, complete initiation of the friction characteristic is stopped (Pol99). A075 The measured values of the leakage measurement or of rotor resistance deviate significantly. The measured values of the leakage measurement or of rotor resistance deviate significantly. The standstill measurement is executed when the converter is powered up. The motor can align itself several times in a certain direction of calculation (for RI) or the sace of drives without any danger: A081 The following description refers to the 1st CBP. For other CBs or the TB see operating instructions for CB board. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for CB board. A083 The following description refers to the CBP. For other CBs or the TB see the operating instructions for Ches or the CBP consequence: No connection is made with the PROFIBUS master. A083 The following description refers to the CBP. For other CBs or the TB see the operating instructions for Ches or the CBP consequence: No connection is made with the PROFIBUS master. A083 The following description refers to the CBP. For other CBP can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master.)	Check cause of alarm (see FD 710)	An active signal is present at binector U068	A064
A072 Automatic initiation of the friction characteristic has been selected, but the drive has not yet been switched on. Note: If the ON command is not given within 30 seconds, the automatic initiation of the friction characteristic is stopped with fault F099. A073 Automatic initiation of the friction characteristic has been interrupted (OFF command or fault). Note: If the drive is not switched on again within 5 minutes, the automatic initiation of the friction characteristic is stopped (F099). A074 Incomplete initiation of fiction characteristic. As there is a lack of enables or due to limitations, complete initiation of the friction characteristic points can be measurement or of rotor resistance deviate significantly. A075 The measured values of the leakage measurement or of rotor resistance deviate significantly. A076 The standstill measurement is executed when the converter is powered up. The motor can align itself several times in a certain direction with this measurement. A078 The standstill measurement is executed when the converter is powered up. The motor can align itself several times in a certain direction with this measurement. A081 The following description refers to the IS see operating instructions for CB board. The ID byte combinations which are being sent from the DP master in the Configuration telegram are not in conformance with the permissible ID byte combinations. (See also Compendium, Chapter 8, Table 8-2-12). Consequence: No connection is made with the PROFIBUS master. CB alarm A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. Consequence: No connection is made with the PROFIBUS master. Consequence: No connection is made with the PROFIBUS master.			(1).	
Automatic initiation of the friction characteristic been switched on. Note: If the ON command is not given within 30 seconds, the automatic initiation of the friction characteristic is stopped with fault F099. Automatic initiation of the friction characteristic has been interrupted (OFF command or fault). Note: If the drive is not switched on again within 5 minutes, the automatic initiation of the friction characteristic is stopped (F099). A074 Incomplete initiation of initiation of the friction characteristic is stopped (F099). A075 The measured values of the leakage measurement or of rotor resistance deviate significantly. A076 The measured values of the leakage measurement or of rotor resistance deviate significantly. The standstill measurement is executed when the converter is powered up. The motor cahalign itself several times in a certair direction with this measurement. A081 The following description refers to the 1st CBP. For other CBs or the TB see operating instructions for the DP master in the configuration telegram are not in configuration refers to the CBP. For other CBs or the TB see the operating instructions for the BDP master. CB alarm A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the BDP master. CG alarm A083 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the opinificant of the proper in the Configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master.				
has been selected, but the drive has not yet been switched on. Note: If the ON command is not given within 30 seconds, the automatic initiation of the friction characteristic is stopped with fault F099. Automatic initiation of the friction characteristic has been interrupted (OFF command or fault). Note: If the drive is not switched on again within 5 minutes, the automatic initiation of the friction characteristic is stopped (F099). A074 Incomplete initiation of interior on the friction characteristic is not possible in both directions. A075 In measured values of the leakage measurement or of rotor resistance deviate significantly. A076 The measured values of the leakage measurement or of rotor resistance deviate significantly. A078 The standstill measurement is executed when the converter is powered up. The motor can align itself several times in a certain direction with this measurement. A078 The following description refers to the 1st CBP. For other CBs or the TB see operating instructions for CB board. The 1D byte combinations which are being sent from the DP master in the CDP. Consequence: No connection is made with the PROFIBUS master. CB alarm A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. CON connection is made with the PROFIBUS master. A083 The following description refers to the 1st.		Energiae drive	Automotic initiation of the friction abarectoristic	
Frict Char Init been switched on.				AUIZ
Note: If the ON command is not given within 30 seconds, the automatic initiation of the friction characteristic is stopped with fault F099. Automatic initiation of the friction characteristic has been interrupted (OFF command or fault). Note: If the drive is not switched on again within 5 minutes, the automatic initiation of the friction characteristic is stopped (F099). A074 Incomplete initiation of friction characteristic. As there is a lack of enables or due to limitations, complete initiation of the friction characteristic is stopped (F099). A075 The measured values of the leakage measurement or of rotor resistance deviate significantly. The standstill measurement is executed when the converter is powered up. The motor can align itself several times in a certain direction with this measurement. A081 The following description refers to the 1st CBP. For other CBs or the TB see the operating instructions for CB board. The ID byte combinations which are being sent from the DP master in the configuration necessary. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for CB board. No valid PPO type can be identified from the configuration telegram of the CDP master. Consequence: No connection is made with the PROFIBUS master. A083 The following description refers to the 1st Consequence: No connection is made with the PROFIBUS master. A083 The following description refers to the CBP. For other CBs or the TB see the operating instruction is made with the PROFIBUS master. A083 The following description refers to the LBP. For other CBs or the TB see the operating instructions for CB board. The following description refers to the CBP. For other CBs or the TB see the operating instruction is made with the PROFIBUS master. A082 The following description refers to the CBP. For other CBs or the TB see the operating instruction is made with the PROFIBUS master.		(Brive status operation 014)		Frict Char Init
A073 Automatic initiation of the friction characteristic has been interrupted (OFF command or fault). Note: If the drive is not switched on again within 5 minutes, the automatic initiation of the friction characteristic has been interrupted (OFF command or fault). Note: If the drive is not switched on again within 5 minutes, the automatic initiation of the friction characteristic is stopped (F099). A074 Incomplete initiation of friction characteristic. As there is a lack of enables or due to limitations, complete initiation of the friction characteristic is not possible in both directions. A075 The measured values of the leakage measurement or of rotor resistance deviate significantly. A075 The measured values of the leakage measurement or of rotor resistance deviate significantly. A078 The standstill measurement is executed when the converter is powered up. The motor can align itself several times in a certain direction with this measurement. A081 The following description refers to the 1st CBP. For other CBs or the TB see operating instructions for CB board. The ID byte combinations which are being sent from the DP master in the configuration telegram are not in configmance with the permissible ID byte combinations. (See also Compendium, Chapter 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. Novalid PPO type can be identified from the configuration telegram of the DP master. Corsequence: No connection is made with the PROFIBUS master. A083 The following description refers to the 1st CBP. For other CBs or the TB see the operating instruction is made with the PROFIBUS master. A083 The following description refers to the LBP. For other CBs or the TB see the operating instruction is made with the PROFIBUS master.			333	
Friction characteristic is stopped with fault Fo99. A073 Automatic initiation of the friction characteristic has been interrupted (OFF command or fault). Interr InitFric Note: If the drive is not switched on again within 5 minutes, the automatic initiation of the friction characteristic is stopped (F099). A074 Incomplete initiation of friction characteristic. As there is a lack of enables or due to limitations, complete initiation of the friction characteristic is not possible in both directions. A075 The measured values of the leakage measurement or of rotor resistance deviate significantly. A075 The measured values of the leakage measurement or of rotor resistance deviate significantly. A076 The standstill measurement is executed when the converter is powered up. The motor of calculation (for RI) or the value of the automatic parameterization remains (for It is forly necessary to check the results their plausibility in the case of drives with this measurement. A081 The following description refers to the 1st CBP. For other CBs or the TB see operating instructions for CB board. The ID byte combinations which are being sent from the DP master in the configuration telegram are not in conformance with the permissible ID byte combinations. (See also Compendium, Chapter 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CBP. For other CBs or the TB see the operating instructions for the CBP. For other CBs or the TB see the operating instructions for the CBP. For other CBs or the TB see the operating instructions for the CBP. For other CBs or the TB see the operating instructions for the CBP. For other CB	•		Note: If the ON command is not given within	
A073 Automatic initiation of the friction characteristic has been interrupted (OFF command or fault). Note: If the drive is not switched on again within 5 minutes, the automatic initiation of the friction characteristic is stopped (F099). A074 Incomplete initiation of friction characteristic. As there is a lack of enables or due to limitations, complete initiation of the friction characteristic is not possible in both directions. A075 The measured values of the leakage measurement or of rotor resistance deviate significantly. A076 The standstill measurement is executed when the converter is powered up. The motor can align itself several times in a certain direction with this measurement. A081 The following description refers to the 1st CBP. For other CBs or the TB see the configuration telegram are not in configuration. A082 Thes following description refers to the CBP. For other CBs or the TB see the operating instructions for the CBP board. A083 The following description refers to the 1st CBP consequence: No connection is made with the PROFIBUS master. A083 The following description refers to the 1st the following description refers to the 1st the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. A083 The following description refers to the 1st the following descri	*			
A073 Automatic initiation of the friction characteristic has been interrupted (OFF command or fault). Note: If the drive is not switched on again within 5 minutes, the automatic initiation of the friction characteristic is stopped (F099). A074 Incomplete initiation of friction characteristic. As there is a lack of enables or due to limitations, complete initiation of the friction characteristic is not possible in both directions. A075 The measured values of the leakage measurement or of rotor resistance deviate significantly. A076 The standstill measurement is executed when the converter is powered up. The motor can align itself several times in a certain direction with this measurement. A081 The following description refers to the 1st CBP. For other CBs or the TB see the operating instructions for the DP master. CB alarm The standstill by byte combinations. (See also Compendium, Chapter 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. A082 The following description refers to the CBP. For other CBs or the CB board. No valid PPO type can be identified from the configuration telegram of the CB board. A083 The following description refers to the 1st. The following description refers to the 1st. The configuration telegram are not in configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board.		. (0	• • • • • • • • • • • • • • • • • • • •	
Interr InitFric Note: If the drive is not switched on again within 5 minutes, the automatic initiation of the friction characteristic is stopped (F099). A074 Incomplete initiation of friction characteristic. As there is a lack of enables or due to limitations, complete initiation of the friction characteristic is not possible in both directions. A075 The measured values of the leakage measurement or of rotor resistance deviate significantly. The standstill measurement is executed when the converter is powered up. The motor can align itself several times in a certain direction with this measurement. A081 The following description refers to the 1st CBP. For other CBs or the TB see operating instructions for CB board. The ID byte combinations which are being sent from the DP master in the configuration telegram are not in configuration. (See also Compendium, Chapte 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the DP master. Consequence: No connection is made with the PROFIBUS master. A083 The following description refers to the 1st The following description refers to the 1st The following description refers to the 1st		Poctifiv any causes of the fault		۸072
Interr InitFric Note: If the drive is not switched on again within 5 minutes, the automatic initiation of the friction characteristic is stopped (F099). A074 Incomplete initiation of friction characteristic. As there is a lack of enables or due to limitations, complete initiation of the friction characteristic is not possible in both directions. A075 The measurement or of rotor resistance deviate significantly. The measurement or of rotor resistance deviate significantly. The standstill measurement is executed when the converter is powered up. The motor can align itself several times in a certain direction with this measurement. A081 The following description refers to the 1st CBP. For other CBs or the TB see operating instructions for CB board. The ID byte combinations. (See also Compendium, Chapter 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. A083 The following description refers to the 1st		Re-energize the drive		A073
If the drive is not switched on again within 5 minutes, the automatic initiation of the friction characteristic is stopped (F099). A074 Incomplete initiation of friction characteristic. As there is a lack of enables or due to limitations, complete initiation of the friction characteristic is not possible in both directions. A075 The measurement or of rotor resistance deviate significantly. The measurement or of rotor resistance deviate significantly. In a standstill measurement is executed when the converter is powered up. The motor can align itself several times in a certain direction with this measurement. A081 The following description refers to the 1st CBP. For other CBs or the TB see operating instructions for CB board. The ID byte combinations. (See also Compendium, Chapter 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. On sequence: No connection is made with the PROFIBUS master. A083 The following description refers to the 1st PROFIBUS master. A083 The following description refers to the DP master. The following description refers to the 1st		The energize the drive.	has been interrupted (Or i communic or iddit).	Interr InitFric
minutes, the automatic initiation of the friction characteristic is stopped (F099). A074 Incomplete initiation of friction characteristic. As there is a lack of enables or due to limitations, complete initiation of the friction characteristic is not possible in both directions. A075 The measured values of the leakage measurement or of rotor resistance deviate significantly. The standstill measurement is executed when the converter is powered up. The motor can align itself several times in a certain direction with this measurement. A081 The following description refers to the 1st CBP. For other CBs or the TB see operating instructions for the DP master. CB alarm The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. A083 The following description refers to the CBP. The other CBs or the TB see the operating instructions for the CB board. The ID byte combinations which are being sent from the DP master in the configuration telegram are not in conformance with the permissible ID byte combinations (See also Compendium, Chapte 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. The following description refers to the 1st			Note:	
A074 Incomplete initiation of friction characteristic. As there is a lack of enables or due to limitations, complete initiation of the friction characteristic is not possible in both directions. A075 The measured values of the leakage measurement or of rotor resistance deviate significantly. A076 The standstill measurement is executed when the converter is powered up. The motor can align itself several times in a certain direction with this measurement. A081 The following description refers to the 1st CBP. For other CBs or the TB see operating instructions for CB board. The ID byte combinations which are being sent from the DP master. Consequence: No valid PPO type can be identified from the configuration telegram are not in smade with the PROFIBUS master. A083 The following description refers to the CBP. For other CBs or the CB board. The following description refers to the CBP. For other CBs or the CB board. The following description refers to the CBP. For other CBs or the CB board. A082 The following description refers to the CBP. For other CBs or the CB board. A083 The following description refers to the CBP. For other CBs or the CB board. A084 The following description refers to the CBP. For other CBs or the CB board. A085 The following description refers to the CBP. For other CBs or the CB board. A086 The following description refers to the CBP. For other CBs or the CB board. A087 The following description refers to the CBP. For other CBs or the CB board. A088 The following description refers to the CBP. For other CBs or the CB board. A089 The following description refers to the CBP. The foll				
Incomplete initiation of friction characteristic. As there is a lack of enables or due to limitations, complete initiation of the friction characteristic is not possible in both directions. The measured values of the leakage measurement or of rotor resistance deviate significantly. A075				
As there is a lack of enables or due to limitations, complete initiation of the friction characteristic is not possible in both directions. A075 The measured values of the leakage measurement or of rotor resistance deviate significantly. The measured values of the leakage measurement or of rotor resistance deviate significantly. The standstill measurement is executed when the converter is powered up. The motor can align itself several times in a certain direction with this measurement. The following description refers to the 1st CBP. For other CBs or the TB see operating instructions for CB board. The ID byte combinations which are being sent from the DP master in the configuration telegram are not in conformance with the permissible ID byte combinations. (See also Compendium, Chapter 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. A082 A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. The following description refers to the CBP. For other CBs or the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. The following description refers to the 1st	rototic -	Cront analysis to be the directions of the		A074
Incompl FricChar Ilimitations, complete initiation of the friction characteristic is not possible in both directions. The measured values of the leakage measurement or of rotor resistance deviate significantly. If individual measured values significantly. If individual measured values significantly automatically not taken into account for calculation (for RI) or the value of the automatic parameterization remains (for It is only necessary to check the results their plausibility in the case of drives we requirements on torque or speed accur for the converter is powered up. The motor can align itself several times in a certain direction with this measurement. A081 The following description refers to the 1st CBP. For other CBs or the TB see operating instructions for CB board. The ID byte combinations which are being sent from the DP master in the configuration telegram are not in conformance with the permissible ID byte combinations. (See also Compendium, Chapter 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. The following description refers to the CBP. For other CBs and instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. The following description refers to the 1st				AU/4
A075 The measured values of the leakage measurement or of rotor resistance deviate significantly. A076 The standstill measurement is executed when the converter is powered up. The motor can align itself several times in a certain direction with this measurement. A081 The following description refers to the 1st CBP. For other CBs or the TB see operating instructions for CB board. The ID byte combinations which are being sent from the DP master in the configuration telegram are not in conformance with the permissible ID byte combinations. (See also Compendium, Chapter 8, Table 8.2-12). Consequence: No valid PPO type can be identified from the configuration telegram of the DP master. CB alarm The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. A083 The following description refers to the 1st				Incompl FricChar
The measured values of the leakage measurement or of rotor resistance deviate significantly. The standstill measurement is executed when the converter is powered up. The motor can align itself several times in a certain direction with this measurement. The following description refers to the 1st CBP. For other CBs or the TB see operating instructions for CB board. The ID byte combinations which are being sent from the DP master. The following description refers to the CBP. For other CBs or the POFIBUS master. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for CB board. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. The following description refers to the 1st				
measurement or of rotor resistance deviate significantly. deviate from the average values, they automatically not taken into account for calculation (for RI) or the value of the automatic parameterization remains (for RI) or the value of the automatic parameterization remains (for RI) or the value of the automatic parameterization remains (for RI) or the value of the automatic parameterization remains (for RI) or the value of the automatic parameterization remains (for RI) or the value of the automatic parameterization remains (for RI) or the value of the automatic parameterization remains (for RI) or the value of the automatic parameterization remains (for RI) or the value of the automatic parameterization remains (for RI) or the value of the automatic parameterization remains (for RI) or the value of the automatic parameterization remains (for RI) or the value of the automatic parameterization remains (for RI) or the value of the automatic parameterization remains (for RI) or the value of the automatic parameterization remains (for RI) or the value of the automatic parameterization remains (for RI) or the value of the automatic parameterization remains (for RI) or the value of the automatic parameterization remains (for RI) or the value of the automatic parameterization remains (for RI) or the value of the automatic parameterization remains (for RI) is only recessary to check the results their plausibility in the automatic parameterization remains (for RI) is only recessary to check the results their plausibility in the automatic parameterization remains (for RI) is only requirements on torque or speed accuration remains (for RI) the standard measurement can be evitional their parameterization remains (for RI) is only requirements on torque or speed accuration remains (for RI) automatic parameterization remains (for RI) automatic parameters and parameters on the standard measure		If individual measured values significan		A075
A078 The standstill measurement is executed when the converter is powered up. The motor can align itself several times in a certain direction with this measurement. The following description refers to the 1st CBP. For other CBs or the TB see operating instructions for CB board. The ID byte combinations which are being sent from the DP master in the configuration telegram are not in conformance with the permissible ID byte combinations. (See also Compendium, Chapter 8, Table 8.2-12). Consequênce: No connection is made with the PROFIBUS master. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. The following description refers to the 1st The following description refers to the 1st	hey are	deviate from the average values, they a		
A078 The standstill measurement is executed when the converter is powered up. The motor can align itself several times in a certain direction with this measurement. A081 The following description refers to the 1st CBP. For other CBs or the TB see operating instructions for CB board. The ID byte combinations. (See also Compendium, Chapter 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. A082 A082 A082 A083 A083 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. A083 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. A083 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. A083 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. A083 The following description refers to the LSt.			significantly.	
A078 The standstill measurement is executed when the converter is powered up. The motor can align itself several times in a certain direction with this measurement. A081 The following description refers to the 1st CBP. For other CBs or the TB see operating instructions for CB board. The ID byte combinations which are being sent from the DP master in the configuration telegram are not in conformance with the permissible ID byte combinations. (See also Compendium, Chapter 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. The following description refers to the 1st The following description refers to the 1st The following description refers to the 1st				
A078 The standstill measurement is executed when the converter is powered up. The motor can align itself several times in a certain direction with this measurement. A081 The following description refers to the 1st CBP. For other CBs or the TB see operating instructions for CB board. The ID byte combinations which are being sent from the DP master in the configuration telegram are not in conformance with the permissible ID byte combinations. (See also Compendium, Chapter 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. The following description refers to the 1st				
A078 The standstill measurement is executed when the converter is powered up. The motor can align itself several times in a certain direction with this measurement. A081 The following description refers to the 1st CBP. For other CBs or the TB see operating instructions for CB board. The ID byte combinations which are being sent from the DP master in the configuration telegram are not in conformance with the permissible ID byte combinations. (See also Compendium, Chapter 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. The following description refers to the CBP. For other CBs or the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. The following description refers to the 1st The following description refers to the 1st				
The standstill measurement is executed when the converter is powered up. The motor can align itself several times in a certain direction with this measurement. A081 The following description refers to the 1st CBP. For other CBs or the TB see operating instructions for CB board. The ID byte combinations which are being sent from the DP master in the configuration telegram are not in conformance with the permissible ID byte combinations. (See also Compendium, Chapter 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No yalid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. The following description refers to the TB see the operating instructions for the CB board. The following description refers to the 1st The following description refers to the 1st				
A081 Align itself several times in a certain direction with this measurement. A081 The following description refers to the 1st CBP. For other CBs or the TB see operating instructions for CB board. The ID byte combinations which are being sent from the DP master in the configuration telegram are not in conformance with the permissible ID byte combinations. (See also Compendium, Chapter 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Corsequence: No connection is made with the PROFIBUS master. The following description refers to the 1st		If the standstill measurement can be ex		A078
with this measurement. A081 The following description refers to the 1st CBP. For other CBs or the TB see operating instructions for CB board. The ID byte combinations which are being sent from the DP master in the configuration telegram are not in conformance with the permissible ID byte combinations. (See also Compendium, Chapter 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. The following description refers to the 1st		without any danger:		
The following description refers to the 1st CBP. For other CBs or the TB see operating instructions for CB board. The ID byte combinations which are being sent from the DP master in the configuration telegram are not in conformance with the permissible ID byte combinations. (See also Compendium, Chapter 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. The following description refers to the 1st				Stands. Meas
CBP. For other CBs or the TB see operating instructions for CB board. The ID byte combinations which are being sent from the DP master in the configuration telegram are not in conformance with the permissible ID byte combinations. (See also Compendium, Chapter 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. The following description refers to the 1st				A 0.04
instructions for CB board. The ID byte combinations which are being sent from the DP master in the configuration telegram are not in conformance with the permissible ID byte combinations. (See also Compendium, Chapter 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. The following description refers to the 1st		New configuration necessary.	CRP. For other CRs or the TR see operating	AU81
The ID byte combinations which are being sent from the DP master in the configuration telegram are not in conformance with the permissible ID byte combinations. (See also Compendium, Chapter 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. A083 The following description refers to the 1st				CB alarm
sent from the DP master in the configuration telegram are not in conformance with the permissible ID byte combinations. (See also Compendium, Chapter 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. A083 The following description refers to the 1st				02 a.a
telegram are not in conformance with the permissible ID byte combinations. (See also Compendium, Chapter 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. A083 The following description refers to the 1st				
permissible ID byte combinations. (See also Compendium, Chapter 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. A083 The following description refers to the 1st				
Compendium, Chapter 8, Table 8.2-12). Consequence: No connection is made with the PROFIBUS master. A082 The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. A083 The following description refers to the 1st				
Consequence: No connection is made with the PROFIBUS master. The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. The following description refers to the 1st			Compandium Chapter 8 Table 8 2-12)	
No connection is made with the PROFIBUS master. The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. The following description refers to the 1st				
The following description refers to the CBP. For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. A083 The following description refers to the 1st				
CB alarm For other CBs or the TB see the operating instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. A083 The following description refers to the 1st				
CB alarm Instructions for the CB board. No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. A083 The following description refers to the 1st		New configuration necessary.		A082
No valid PPO type can be identified from the configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. A083 The following description refers to the 1st				CB alarm
configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. A083 The following description refers to the 1st			manuchors for the CD board.	OD alallil
configuration telegram of the DP master. Consequence: No connection is made with the PROFIBUS master. A083 The following description refers to the 1st			No valid PPO type can be identified from the	
No connection is made with the PROFIBUS master. A083 The following description refers to the 1st				
master. A083 The following description refers to the 1st				
A083 The following description refers to the 1st				
				4000
CDI . I OI Other CD3 OI the TD see the				AU83
CB alarm operating instructions for the CB board.				CB alarm
Speciality in the Special Control of the Spec				
No net data or invalid net data (e.g. complete			No net data or invalid net data (e.g. complete	
control word STW1=0) are being received			control word STW1=0) are being received	
from the DP master.				
Consequence: The process data are not passed on to the				
The process data are not passed on to the dual port RAM. If P722 (P695) is not equal to				
zero, this will cause the fault message F082 to				
be tripped.			•	7

Number / Alarm	Cause	Counter-measure
A084	The following description refers to the 1st	
CD alama	CBP. For other CBs or the TB see the	
CB alarm	operating instructions for the CB board.	
	The telegram traffic between the DP master	
	and the CBP has been interrupted (e.g. cable	
	break, bus cable pulled out or DP master	
	powered down).	
	Consequence: If P722 (P695) is not equal to zero, this will	•
	cause the fault message F082 to be tripped.	
A085	The following description refers to the 1st	. 60
	CBP. For other CBs or the TB see the	
CB alarm	operating instructions for the CB board.	
	The CBP does not generate this alarm!	
A086	The following description refers to the 1st	, U
	CBP. For other CBs or the TB see the	
CB alarm	operating instructions for the CB board.	
	Failure of the heart best secretar as the first	
	Failure of the heart-beat counter on the basic unit. The heartbeat counter on the basic unit is	
	no longer being incremented. The	
	communication between the CBP and the	
	basic board is disturbed.	
A087	The following description refers to the 1st	
CB alarm	CBP. For other CBs or the TB see the operating instructions for the CB board.	
CD didilli	operating instructions for the CB board.	
	Fault in the DPS manager software of the	
	CBP.	
A088	See user manual for CB board	
CB alarm		
A089	See user manual for CB board	
7.000	Alarm of the 2nd CB board corresponds to	
CB alarm	A81 of the 1st CB board	
A090	See user manual for CB board	
CB alarm	Alarm of the 2nd CB board corresponds to A82 of the 1st CB board	
A091	See user manual for CB board	
7.00	Alarm of the 2nd CB board corresponds to	
CB alarm	A83 of the 1st CB board	
A092	See user manual for CB board	
CB alarm	Alarm of the 2nd CB board corresponds to A84 of the 1st CB board	
A093	See user manual for CB board	
	Alarm of the 2nd CB board corresponds to	
CB alarm	A85 of the 1st CB board	
A094	See user manual for CB board	
CB alarm	Alarm of the 2nd CB board corresponds to	
CB alarm A095	A86 of the 1st CB board Alarm of the 2nd CB board. Corresponds to	
	A87 of the 1st CB board	
CB alarm		
1000	See user manual for CB board	
A096	See user manual for CB board	
CB alarm	Alarm of the 2nd CB board corresponds to A88 of the 1st CB board	
A097	See user manual for TB board	
TB alarm 1		
not Compact DLUC		
not Compact PLUS		

Number / Alarm	Cause	Counter-measure
A098	See user manual for TB board	
TB alarm 1		
not Compact PLUS A099	See user manual for TB board	
A099	See user manual for 1B board	
TB alarm 1		
not Compact PLUS		•
A100	See user manual for TB board	. (0
TB alarm 1		
not Compact PLUS A101	See user manual for TB board	
Alui	See user manual for 1B board	~ 0
TB alarm 1		
not Compact PLUS		
A102	See user manual for TB board	
TB alarm 1		
not Compact PLUS A103	See user manual for TB board	K'O
A103	See user manual for 15 board	
TB alarm 1		
not Compact PLUS	×	
A104	See user manual for TB board	
TB alarm 1		
not Compact PLUS A105	See user manual for TB board	
	Cee deel manda for 15 board	
TB alarm 1		
not Compact PLUS		
A106	See user manual for TB board	
TB alarm 1	~ 0	
. 0		
not Compact PLUS A107	See user manual for TB board	
-	33.3	
TB alarm 1	X	
not Compact PLUS		
A108	See user manual for TB board	
TB alarm 1		
	/ 1	
not Compact PLUS A109	See user manual for TB board	
	1	
TB alarm 1		
not Compact PLUS		
A110	See user manual for TB board	
TB alarm 1		
not Compact PLUS		

Number / Alarm	Cause	Counter-measure
A111	See user manual for TB board	
TB alarm 1		
not Compact PLUS	1,	
A112	See user manual for TB board	
TB alarm 1		
		♦
not Compact PLUS A113	See user manual for TB board	
	000 000:	\ \S
TB alarm 2		
not Compact PLUS		
A114	See user manual for TB board	
TB alarm 2		
TD alaitil 2		
not Compact PLUS		
A115	See user manual for TB board	
TB alarm 2		
mat Camera at DI LIO		
not Compact PLUS A116	See user manual for TB board	W. O
ATTO	occ user manual for 15 board	
TB alarm 2		
not Compact PLUS		
A117	See user manual for TB board	
TD alama 0		
TB alarm 2		
not Compact PLUS		
A118	See user manual for TB board	
TB alarm 2		
not Compact PLUS A119	See user manual for TB board	
Alla	See user manual for 15 board	
TB alarm 2	~ · U	
not Compact PLUS	. ()	
A120	See user manual for TB board	
TD alams: 0		
TB alarm 2	X	
not Compact PLUS		
A121	See user manual for TB board	
TB alarm 2		
	/ 1	
not Compact PLUS	See year manual for TD board	
A122	See user manual for TB board	
TB alarm 2	*	
not Compact PLUS		
A123	See user manual for TB board	
TB alarm 2		
not Compact PLUS		
1 1 1 1 1 2 2 2 2		

Number / Alarm	Cause	Counter-measure
A124	See user manual for TB board	
TB alarm 2		
not Compact PLUS		
A125	See user manual for TB board	
TB alarm 2		
not Compact PLUS		•
A126	See user manual for TB board	
TD -l 0		
TB alarm 2		
not Compact PLUS		
A127	See user manual for TB board	
TB alarm 2		
ID didiiii Z		
not Compact PLUS		
A128	See user manual for TB board	
TB alarm 2		
1 D didini 2		
not Compact PLUS		
A129	Machine data 1 (position encoder type/axis type) is 0 (axis does not exist).	You must assign a valid value to machine data 1 in order to operate the axis.
Axis does not exist -	type) is 0 (axis does not exist).	I in order to operate the axis.
machine data 1 = 0	Effect:	
	Operation of the axis is inhibited and the	
A130	position controller is deactivated. The "in operation" [IOP] checkback signal was	Activate control signals [OFF1], [OFF2],
A130	missing when a traversing command was	[OFF3] and "enable controller" [ENC].
Operating conditions	initiated. The following causes inhibit the "in	
do not exist	operation" checkback signal (status bit No.2, refer to function diagram sheet 200):	-If checkback signals [OFF2] and/or [OFF3] are missing, check the supply of control word
	Terer to function diagram sheet 200).	1 (MASTERDRIVE function diagram, sheet
	-Control signals [OFF1], [OFF2], [OFF3]	180).
	and/or "enable controller" [ENC] are not activated.	Analyza the greeted fault number
	activated.	-Analyze the queued fault number [FAULT_NO], remedy the fault, and then
	-Checkback signals [OFF2] and/or [OFF3] are	cancel the fault using the acknowledge fault
	not activated.	[ACK_F] control signal.
	-A fault [FAULT] is active.	Note:
	Widdle [West] is delive.	To activate the "in operation" [IOP] status
	Effect:	again, you must deactivate [OFF1] and then
A131	The traversing command is inhibited.	activate it again. Check the activation of control signal [OFF1]
AISI	Control signal [OFF1] was deactivated while a traversing command was being executed.	from the user program.
OFF1 missing		man and accorpt agreemen
	Effect:	
	The drive is brought to a standstill via a ramp (machine data 43: deceleration time during	
	faults). There is a subsequent pulse disable.	
A132	-Control signal [OFF2] was deactivated while a	-Check the activation of control signal [OFF2]
OFF2 missing	traversing command was being executed.	from the user program.
Of 12 missing	-Checkback signal [OFF2] was deactivated	-If checkback signal [OFF2] is missing, check
	while a traversing command was being	the supply of control word 1 (MASTERDRIVE
_	executed.	function diagram, sheet 180).
_	Effect:	Note:
•	The pulse disable is initiated immediately. If	To activate the "in operation" [IOP] status
	the motor is not braked, it coasts down.	again, you must deactivate [OFF1] and then
		activate it again.

Number / Alarm	Cause	Counter-measure
A133	-Control signal [OFF3] was deactivated while a	-Check the activation of control signal [OFF3]
0550	traversing command was being executed.	from the user program.
OFF3 missing	-Checkback signal [OFF3] was deactivated while a traversing command was being executed.	-If checkback signal [OFF3] is missing, check the supply of control word 1 (MASTERDRIVE function diagram, sheet 180).
	Effect: The motor decelerates at the current limit. There is a subsequent pulse disable.	Note: To activate the "in operation" [IOP] status again, you must deactivate [OFF1] and then activate it again.
A134 Enable Controller ENC	The "enable controller" [ENC] control signal was deactivated while a traversing command was being executed (control bit No.3 "Inverter Table", refer to function diagram, about 190)	Check the activation of the "enable controller" [ENC] control signal from the user program.
missing	Enable", refer to function diagram, sheet 180) Effect: The pulse disable is initiated immediately. If the motor is not braked, it coasts down.	
A135	Actual position value not o.k. from position sensing (B0070 / B0071)	-Check interconnection of B0070 and B0071, -check position encoder and evaluation board,
Actual position value not o.k		-check encoder cable.
A136 Machine data 1	Machine data 1 (position encoder type/axis type) was changed.	If machine data 1 has been changed, the "reset technology" [RST] control signal must
changed - RESET	Effect:	be activated. Alternatively switch the MASTERDIVES electronic power supply off
necessary	The activation of traversing commands is inhibited.	and on again
A137	The same axis assignment (machine data 2)	A unique axis assignment must be entered for all axes on an M7-FM. For example, it is not
Axis assignment incorrect	was entered for several axes (M7 only, not significant for the F01 technology option).	allowed to define two X axes.
	Effect: The activation of traversing commands is inhibited.	
A138 Axis assignment of roll	The NC block contains an axis number which is defined as a roll feed axis but the axis type is defined as an incremental or absolute	-Axis type 1 or 2:The block is not allowed to contain an axis number which is defined as a roll feed (M7 only).
feed incorrect	position encoder (machine data 1 = 1 or 2). (M7 only, not significant for the F01 technology option) .	-Axis type 3:The axis number of the roll feed must be specified in every NC block.
	The NC block for a roll feed axis type (machine data 1 = 3) contains: -No axis number (X, Y, Z)	
	-An incorrect axis number	
	Effect: NC program execution is inhibited or aborted.	
A140	The following error limit for standstill was exceeded at standstill:	-Check and correct the machine data.
Following error in standstill	-Following error monitoring - at standstill	-Optimize the speed/current controller,
	(machine data 14) was entered incorrectly.	-Rectify mechanical problem.
	The value entered for "in position - exact stop window" (machine data 17) is greater than the value in "following error monitoring - at standstill" (machine data 14).	
	-The axis was pushed out of position mechanically.	
4	Effect: The position control system is deactivated and the axis decelerates via "deceleration time during errors" (machine data 43).	

Number / Alarm	Cause	Counter-measure
A141	The following error limit for motion was exceeded during a traversing movement:	-Check and correct the machine data.
Following error in motion	-Following error monitoring - in motion (machine data 15) was entered incorrectly.	-Check the actual position value (speed- controlled operation); check position encoder, evaluator module and encoder lead.
	-The mechanical system cannot follow the commands of the position controller.	-Optimize the position controller or the speed controller.
	-Actual position value invalid	-Check the mechanical system.
	-Incorrect optimization of the position controller or speed controller.	S
	-The mechanical system is sluggish or blocked.	
	Effect: The position control system is deactivated and the drive decelerates via "deceleration time during faults" (machine data 43).	
A142 In position - timer	The "in position - exact stop window" was not reached within the time specified in in position - timer monitoring":	-Check and correct the machine dataOptimize the position controller or speed
monitoring	-In position - exact stop window (machine data 17) too small	controllerCheck the mechanical system.
	-In position - timer monitoring (machine data 16) too short	
	-Position controller or speed controller not optimized	
	-Mechanical causes Effect:	
A145	The position control system is deactivated. The "digital input" with the "disable actual	The "digital input" for "disable actual value"
Actual-value disable not allowed - axis	value" function was actuated while the roll feed was running.	can only be actuated when the axis is stationary.
standstill	Effect: The axis movement is stopped via the deceleration ramp, the "disable actual value" function is not executed.	
A146 Direction of movement not allowed	A positioning movement was aborted. When attempting to resume the movement at the point of interruption, the roll feed would have had to travel in the opposite direction to reach	Move the axis in front of the target position in setup mode before continuing.
	the programmed target position. This is inhibited by the setting of machine data 37 "response after abort".	
	There are various possible reasons for the axis crossing the target position when a positioning movement is aborted:	
V /	-Motor coastdown	
	-The axis was moved intentionally, e.g. in setup mode.	
*	Effect: The axis movement is inhibited.	

Number / Alarm	Cause	Counter-measure
A148	The current deceleration value is 0, e.g.	This fault should not normally occur. It is used
	because of a RAM storage error or an error in	as an emergency stop feature for the
Deceleration = 0	the technology firmware.	technology software.
	F# .	Replace the hardware (M7; MCT).
	Effect:	
	The position control system is deactivated and	
	the drive is decelerated via the "deceleration	
A149	time during errors" (machine data 43). Internal error in the technology software.	This foult should not normally occur. It is used
A149	internal error in the technology software.	This fault should not normally occur. It is used as an emergency stop feature for the
Distance to go negative	Effect:	technology software.
Distance to go negative	The position control system is deactivated and	toormology contware.
	the drive is decelerated via the "deceleration	
	time during errors" (machine data 43).	
A150	The selected NC program contains a slave	The same slave axis cannot be used
	axis which is already being used by another	simultaneously by several NC programs.
Slave axis already	master axis (M7 only, not significant for the	
allocated to other	F01 technology option).	
master axis		
	Example:	
	NC program 1, started in axis X, contains NC	4
	blocks for axes X and Y. NC program 2 is	
	started in axis Z and contains NC blocks for	
	axes Z and Y. This program is denied with	_ (// *
	warning 150, because axis Y is already being	K.O
	used by program 1.	
	Effect:	
	NC program execution is inhibited or aborted.	
A151	The slave axis required by the master axis is	The slave axis must be switched to "slave"
7,101	not in "slave" mode (M7 only, not significant	mode.
Slave axis operating	for the F01 technology option).	3,7000
mode not allowed	to me to the money	
	Effect:	
	NC program execution is inhibited or aborted,	
	the axis is brought to a standstill via the	
	deceleration ramp.	
A152	The "slave" mode was deselected in the slave	The slave axis must remain switched to
	axis during the traversing movement (M7 only,	"slave" mode.
Slave axis operating	not significant for the F01 technology option).	
mode changed	Effect	
	Effect:	
	NC program execution is inhibited or aborted, the axis is brought to a standstill via the	
	deceleration ramp.	
A153	A warning is active in the slave axis required	The NC program will only run if all of the axes
	by the master axis (M7 only, not significant for	it needs are error-free. To clear this warning,
Error in slave axis	the F01 technology option).	you must first clear all the warnings in the
	X,	slave axis.
	Effect;	
	NC program execution is inhibited or aborted,	
	the axis is brought to a standstill via the	
	deceleration ramp.	
A154	The "follow-up mode" [FUM] control signal is	Deactivate follow-up mode in the slave axis.
	active in the slave axis required by the master	
Follow-up mode in	axis. A slave axis which is switched to follow-	
slave axis active	up mode cannot be operated by the master	
	axis (M7 only, not significant for the F01	
X/	technology option).	
	Effect:	
▼	NC program execution is inhibited or aborted,	
	the axis is brought to a standstill via the	
	deceleration ramp.	
_	accordation ramp.	<u> </u>

Number / Alarm	Cause	Counter-measure
A155	The "reset" [RST] control signal is active in the	Cancel the "reset" [RST] control signal in the
	slave axis required by the master axis. A slave	slave axis.
Reset in slave axis	axis with an active reset cannot be used by the	
active	master axis (M7 only, not significant for the	
	F01 technology option.	
	Effect:	
	NC program execution is inhibited or aborted,	
	the axis is brought to a standstill via the	
	deceleration ramp.	•
A156	An NC program was started in which a slave	Axes defined as roll feed axes can only be
	axis is defined as a roll feed axis type (M7	used in dedicated NC programs.
Axis type (MD1) of	only, not significant for the F01 technology	
slave axis not allowed	option).	
	The warning is output in the master axis and	
	indicates an illegal axis type in the slave axis.	A*(U)
	maiotico an mogal axio typo in the clave axio.	
	Effect:	
	NC program execution is inhibited or aborted,	
	the axis is brought to a standstill via the	
A 4 0 0	deceleration ramp.	
A160	The value entered in level 1 or level 2 for the	Define a permissible velocity level for level 1 and/or level 2. The permissible value range is
Setup speed = 0	[F_S] velocity level in setup mode is zero.	between 0.01 [1000*LU/min] and "traversing
Setup Speed = 0	Effect:	velocity - maximum (machine data 23).
	The axis movement is inhibited.	velocity maximum (macrime data 20).
A161	The velocity value entered for "reference point	Enter a permissible value for the approach
	- approach velocity" (machine data 7) is zero.	velocity. The permissible value range is
Reference approach		between 0.01 [1000*LU/min] and "traversing
velocity = 0	Effect:	velocity - maximum (machine data 23).
A 4 0 0	The axis movement is inhibited.	Fatana a seria 'h la calla fan (h a safana a s
A162	The velocity value entered for "reference point - reducing velocity" (machine data 6) is zero.	Enter a permissible value for the reference point -reducing velocity. The permissible value
Reference point -	- reducing velocity (machine data o) is zero.	range is between 0.01 and 1000
reducing velocity = 0	Effect:	[1000*LU/min].
3 ,	The axis movement is inhibited or stopped.	,
A165	The MDI block number [MDI_NO] specified in	Define an MDI block number [MDI_NO]
	the control signals is greater than 11.	between 0 and 10.
MDI block number not	Effects	
allowed	Effect: The axis movement is inhibited.	
A166	The "start" [STA] control signal was activated	Use the correct sequence: data transfer
A100	in MDI mode without initially transferring a	followed by axis start.
No position has been	positional value to the selected MDI block.	Tollowed by axio start.
programmed in MDI		
mode	Effect:	
A 4 0 7	The axis movement is inhibited.	
A167	The "start" [STA] control signal was activated	Use the correct sequence: data transfer
No velocity has been	in MDI mode without initially transferring a velocity value to the selected MDI block.	followed by axis start.
programmed in MDI	Volocity value to the selected MIDI Block.	
mode	Effect:	
	The axis movement is inhibited.	
A168	G91 (incremental dimensions) was defined in	The MDI on-the-fly function only allows G90
	the MDI block as the 1st G function for the	(absolute dimensions) as the 1st G function.
G91 not allowed with	MDI on-the-fly function.	
MDI on the fly	Effects	
	Effect: The axis movement is inhibited or stopped via	
	the deceleration ramp.	
A169	-Control signal "reset technology" [RST]	Ensure that the control signals are activated
<u> </u>	activated	correctly.
Start conditions for		_
flying MDI do not exist	-Control signal "follow-up mode" [FUM]	
	activated	
	Effect:	
	The "MDI on-the-fly" function is not executed.	
		<u> </u>

Number / Alarm	Cause	Counter-measure
A170	An NC block was started in single-block mode	Transfer the block.
	although a block has not yet been transferred.	
Single block mode		
block does not exist	Effect:	
A 1 7 2	NC block execution is inhibited.	-Transfer the program to the technology.
A172	The program number specified in [PROG_NO] for automatic mode is not stored in the	- Transfer the program to the technology.
Program with this	memory of the technology.	-Select the correct program number.
number does not exist		Δ
	Effect:	
	NC program execution is inhibited.	
A173	The program number specified in [PROG_NO]	The permissible range for program numbers is
Drogram number not	for automatic mode is not allowed.	between 1 and 200.
Program number not allowed	Effect:	
anowed	NC program execution is inhibited.	
A174	The program number [PROG_NO] was	The program number must not be changed
	changed while the program was running.	while the program is running.
Program number		
changed during	Effect:	
traversing	NC program execution is aborted and the axis	
	or axes are brought to a standstill via the deceleration ramp.	
A175	The decoded NC block is not terminated with	Correct the block.
76	the following block identifier "0".	
No block end		The last block in the sequence must contain
programmed	You can use the "output actual values -	the following block identifier "0".
	decoder error location" task to read out the	
	program number and block number where the	
	block decoder detected an error.	
	Effect:	
	NC program execution is inhibited or aborted.	
	Moving axes are stopped via the deceleration	
	ramp.	
A177	The program number for the main program (level 0), which was transferred with the block	Specify an existing main program number.
Prog. number of block	search function, does not exist.	
search forwd. does not	Course randicity account cours	
exist	Effect:	
	NC program execution is inhibited.	
A178	-The program number for the main program	For the block search function, the selected
Program number of	(level 0), which was transferred with block search, is different from the selected program	program number [PROG_NO] must be specified as the program number for the main
block search forward	number.	program.
not allowed		p.og.a.m
	-No breakpoint is known for the "automatic	
	block search" function (a program abort has	
	not yet occurred).	
	-A different program number is stored as the	
	breakpoint for the "automatic block search"	
	function.	
	74	
	Effect:	
A 4 7 0	NC program execution is inhibited.	For the block or such for effective and effective
A179	The subprogram number specified with block search for level 1 or level 2 does not exist.	For the block search function, an existing program number must be specified as the
Prog.No.of block srch	Search for level 1 of level 2 does not exist.	subprogram number for level 1 or level 2.
fwd level 1/2 does not	Effect:	535p. 5g. a.m. mambol 101 10401 1 01 10401 2.
exist	NC program execution is inhibited.	
A180	The subprogram number transferred with	For the block search function, the subprogram
	block search for level 1 is not the same as the	number specified in the NC block must be
Prog.no. of block	subprogram number in the NC block.	specified as the subprogram number for level
search forward level 1	Effect:	1.
Citio.	NC program execution is inhibited.	
	- 1 - 3	J.

Number / Alarm	Cause	Counter-measure
A181	The subprogram number transferred with	For the block search function, the subprogram
Prog.no. of block	block search for level 2 is not the same as the subprogram number in the NC block.	number specified in the NC block must be specified as the subprogram number for level
search forward level 2	Subprogram number in the NC block.	2.
<> cmd.	Effect:	
	NC program execution is inhibited.	
A183	The block number for the main program (level	For the block search function, an existing
Block no. of block	0), which was transferred with block search, does not exist in the main program.	block number must be specified as the block number for the main program.
search fwd I. 0 does	acconditional main program	namber for the main program
not exist	Effect:	
A184	NC program execution is inhibited. The block number for the main program (level	For the block search function, a block number
A104	0), which was transferred with block search,	with a subprogram call must be specified as
Block no. of block	does not contain a subprogram call for	the block number for the main program (level
search forward is no	subprogram level 1.	0) if a block search is to be performed in
UP call	Effect:	subprogram level 1
	NC program execution is inhibited.	
A185	The block number for subprogram level 1,	For the block search function, a block number
L	which was transferred with block search, does	which exists in this subprogram must be
Block no. of block search forward does	not exist in the subprogram.	specified as the block number for subprogram level 1.
not exist	Effect:	level 1.
THOSE OXIOE	NC program execution is inhibited.	
A186	The block number for subprogram level 1,	For the block search function, a block number
Block no of block	which was transferred with block search, does	with a subprogram call must be specified as the block number for subprogram level 1 if a
search fwd level 1 is no	not contain a subprogram call for subprogram level 2.	block search is to be performed in subprogram
UP call	N .	level 2.
	Effect:	
A187	NC program execution is inhibited. The block number for subprogram level 2,	For the block search function, a block number
Alor	which was transferred with block search, does	which exists in this subprogram must be
Block no. of block	not exist in the subprogram.	specified as the block number for subprogram
search forward does	E#	level 2.
not exist	Effect: NC program execution is inhibited.	
A188	The remaining loop count transferred with	For the block search function, it is only allowed
	block search for subprogram level 1 or 2 is	to specify a remaining loop count between 0
Remaining no of loops	greater than the programmed loop count.	and the programmed loop count-1.
block search fwd not allowed	Effect:	
anomoa	NC program execution is inhibited.	
A190	The NC block which was read in contains the	Program the digital input for the desired
Digital input not	"inprocess measurement" or "set actual value on-the-fly" function, although a digital input	function.
programmed	has not been programmed for this function	
programmou	(machine data 45).	
	Effect: NC program execution is inhibited or aborted,	
	the axis is brought to a standstill via the	
	deceleration ramp.	
A191	Although the "external block change" function	-Correct the program.
Digital input not	was programmed, the digital input was not actuated in order to trigger the external block	Chock the actuation of the digital input
actuated	change.	-Check the actuation of the digital input.
	Effect:	
•	The NC program is interrupted, the axis is brought to a standstill via the deceleration	
A	ramp.	
	l	J.

Number / Alarm	Cause	Counter-measure
A195	-Negative software limit switch position approached	-Check the machine data and the NC program.
Negative overtravel reached	-"Software limit switches - negative" (machine data 12) entered incorrectly	-Check the encoder actual value.
	-The programmed position is less than the negative software limit switch.	
	-"Reference point - coordinate" (machine data 3) is less than the negative software limit switch.	5
	-Incorrect encoder actual value	
	Effect: The axis movement is stopped via the deceleration ramp.	10
A196 Positive overtravel	-Positive software limit switch position approached	-Check the machine data and the NC programs.
reached	-"Software limit switches - positive" (machine data 13) entered incorrectly"	-Check the encoder actual value.
	-The programmed position is greater than the positive software limit switch	
	-"Reference point - coordinate" (machine data 3) is greater than the positive software limit switch	
	-Incorrect encoder actual value	
	Effect: The axis movement is stopped via the deceleration ramp.	
A200	No position has been programmed in the NC block for the roll feed version, although the	The axis number and the positional value must be specified in every NC block for the roll feed
No position has been programmed in	axis number of the roll feed is specified.	version.
Automatic mode	Effect: NC program execution is inhibited or aborted, the axis is brought to a standstill via the deceleration ramp.	
A201	The decoded NC block needs a path or axis velocity.	When using linear interpolation with path velocity (G01), a path velocity must be defined
No velocity has been programmed in	Effect:	with F. When using chaining with axis velocity (G77), the axis velocities must be defined with
Automatic mode	NC program execution is inhibited or aborted, the axis is brought to a standstill via the deceleration ramp.	FX, FY, etc. When using roll feed with axis velocity (G01), the velocity must be defined with F.

Number / Alarm	Cause	Counter-measure
A202	An axis which does not exist was detected in	Correct the NC block.
Axis unknown	the decoded NC block. A logical name (X, Y, Z, A, B, C) must be assigned to each axis with	
AXIS UTIKITOWIT	machine data 2 (axis assignment). Only these	
	logical axis names can be used in the NC	
	block. These errors cannot normally occur,	
	since the logical axis names are verified when	
	the NC blocks are entered.	
	Exception: Machine data 2 (axis assignment)	*
	is changed afterwards.	. 60
	The NC program number and NC block	
	number in which the NC block decoder	
	detected the error can be read out with the	
	"output actual values – decoder error location"	• • • • • • • • • • • • • • • • • • • •
	task.	
	Effect:	
	NC program execution is inhibited or aborted,	
	the axis is brought to a standstill via the deceleration ramp.	
A203	The NC block which was read in contains an	-MDI mode:Only G90 (absolute dimensions) or
A200	illegal 1st G function.	G91 (incremental dimensions) can be entered
1st G-function not	inegal 1st & function.	as the 1st G function. Only G91 is allowed for
allowed	The NC program number and NC block	the roll feed version.
	number in which the NC block decoder	10 0 10 0 10 10 10 10 10 10 10 10 10 10
	detected the error can be read out with the	-Automatic/single-block mode:Define a legal
	"output actual values - decoder error location"	1st G function according to the table (see the
	task.	Programming Guide).
	Effect:	
	The axis movement is inhibited or stopped via	
	the deceleration ramp.	
A204	The NC block which was read in contains an	-MDI mode:Only G30 to G39 (acceleration
	illegal 2nd G function.	override) can be entered as the 2nd G
2nd G-function not		function.
allowed	The NC program number and NC block	
	number in which the NC block decoder	-Automatic/single-block mode:Define a legal
	detected the error can be read out with the	2nd G function according to the table (see the
	"output actual values - decoder error location"	Programming Guide).
	task.	
	Effect:	
	The axis movement is inhibited or stopped via the deceleration ramp.	
A205	The NC block which was read in contains an	-MDI mode:No 3rd G function is allowed.
	illegal 3rd G function.	
3rd G-function not	X	-Automatic/single-block mode:Define a legal
allowed	The NC program number and NC block	3rd G function according to the table (see the
	number in which the NC block decoder	Programming Guide).
	detected the error can be read out with the	
	"output actual values - decoder error location"	
	task.	
	New .	
	Effect:	
	The axis movement is inhibited or stopped via	
	the deceleration ramp.	

Number / Alarm	Cause	Counter-measure
A206	The NC block which was read in contains an illegal 4th G function.	-MDI mode:No 4th G function is allowed.
4th G-function not allowed	The NC program number and NC block number in which the NC block decoder detected the error can be read out with the "output actual values - decoder error location" task.	-Automatic/single-block mode:Define a legal 4th G function according to the table (see the Programming Guide).
	Effect: The axis movement is inhibited or stopped via the deceleration ramp.	,60
A208	A D number greater than 20 was found in the decoded NC block.	Correct the NC block.
D-number is not allowed	The NC program number and NC block number in which the NC block decoder detected the error can be read out with the "output actual values - decoder error location" task.	
	Effect: The axis movement is inhibited or stopped via the deceleration ramp.	
A210 Interpolation of 3 axes not allowed	The decoded NC block contains an interpolation of 3 or more axes. The NC program number and NC block number in which the NC block decoder detected the error can be read out with the	Correct the NC block. Only 2D interpolation is allowed.
	"output actual values - decoder error location" task. Effect: NC program execution is inhibited or aborted, the axis is brought to a standstill via the	
	deceleration ramp.	
A211	G function G68 (shortest path for rotary axis) was detected in the decoded NC block,	Correct the NC block.
Shortest distance G68 and G91 not allowed	although G91 (incremental dimensions) is active. Example: N10 G91 G68 X20.000	Function G68 can only be programmed in association with G90 (absolute dimensions).
	The NC program number and NC block number in which the NC block decoder detected the error can be read out with the "output actual values - decoder error location" task. Effect: NC program execution is inhibited or aborted, the axis is brought to a standstill via the	

Number / Alarm	Cause	Counter-measure
A212	A different axis was programmed in the NC	Correct the NC program. The axis used in the
	block following a special function (M7 only).	NC block with the special function must also
Special function and	F	be programmed in the next NC block.
axis combination not	Example:	
allowed	N10 G50 X100 F1000 N15 G90 Y200 incorrect	
	N15 G90 Y200 incorrect	
	N13 C30 A200 Collect	
	The NC program number and NC block	
	number in which the NC block decoder	_
	detected the error can be read out with the	
	"output actual values - decoder error location"	
	task.	
	Effect:	
	NC program execution is inhibited or aborted,	. • / / /
	the axis is brought to a standstill via the	
A 0.4.0	deceleration ramp. The decoded NC block contains several D	Correct the NC block
A213		Correct the NC block.
Multiple D-number not	numbers.	
allowed	Example:	
alloweu	N1 G41 D3 D5.	
	N1 041 D3 D3.	
	The NC program number and NC block	\\/
	number in which the NC block decoder	
	detected the error can be read out with the	
	"output actual values - decoder error location"	
	task.	
	Effect:	
	NC program execution is inhibited or aborted,	
	the axis is brought to a standstill via the	
	deceleration ramp.	
A214	The decoded NC block contains several	Correct the NC block.
Multiple esselention	mutually exclusive G functions from the	
Multiple acceleration behaviour not allowed	acceleration override group (G30 to G39).	
benaviour not allowed	Example:	
	N1 G34 G35	
A245	111 304 300	
	The NC program number and NC block	
	number in which the NC block decoder	
	detected the error can be read out with the	
	"output actual values - decoder error location"	
	task.	
	Effect:	
	NC program execution is inhibited or aborted,	
	the axis is brought to a standstill via the	
	deceleration ramp.	Correct the NC block
A215	The decoded NC block contains several	Correct the NC block.
Multiple special	mutually exclusive G functions from the	
Multiple special functions not allowed	special function group (G87, G88, G89, G50, G51).	
unctions not allowed	(331).	
	Example:	
47	N1 G88 G50	
	555 555	
	The NC program number and NC block	
	number in which the NC block decoder	
4	detected the error can be read out with the	
	"output actual values - decoder error location"	
	task.	
	Effect:	
	NC program execution is inhibited or aborted,	
	the axis is brought to a standstill via the	
~	deceleration ramp.	

Number / Alarm	Cause	Counter-measure
A216	The decoded NC block contains several	Correct the NC block.
	mutually exclusive G functions from the block	
Multiple block transition	transition group (G60, G64, G66, G67).	
not allowed	Evenne	
	Example: N1 G64 G66 X1.000 FX100.00	
	141 C04 C00 X1:000 1 X100:00	
	The NC program number and NC block	
	number in which the NC block decoder	•
	detected the error can be read out with the	
	"output actual values - decoder error location"	. (6
	task.	
	Effect:	
	NC program execution is inhibited or aborted,	
	the axis is brought to a standstill via the	
	deceleration ramp.	
A217	The decoded NC block contains the same axis	Correct the NC block.
Multiple ovic	more than once.	
Multiple axis programming not	Example:	
allowed	N1 G90 G01 X100.000 X200.000 F100.00	
	111 210 201 7.100.000 7.200.000 7.100.00	
	The NC program number and NC block	
	number in which the NC block decoder	
	detected the error can be read out with the	
	"output actual values - decoder error location"	
	task.	
	Effect:	
	NC program execution is inhibited or aborted,	
	the axis is brought to a standstill via the	
	deceleration ramp.	
A218	The decoded NC block contains several	Correct the NC block.
Multiple peth condition	mutually exclusive G functions from the	
Multiple path condition not allowed	preparatory function group (G00/G01/G76/G77).	
not allowed	(600/601/610/611).	
	Example:	
	N1 G01 (linear interpolation) G77 (chaining)	
	X10 F100.	
	TI NO	
	The NC program number and NC block number in which the NC block decoder	
	detected the error can be read out with the	
	"output actual values - decoder error location"	
	task.	
	Effect:	
	NC program execution is inhibited or aborted, the axis is brought to a standstill via the	
	deceleration ramp.	
A219	The decoded NC block contains several	Correct the NC block.
	mutually exclusive G functions from the	
Multiple dimensions	dimensional notation group (G90/G91).	
specification not	F	
allowed	Example: N1 G90 G91.	
	NI G90 G91.	
	The NC program number and NC block	
	number in which the NC block decoder	
	detected the error can be read out with the	
_	"output actual values - decoder error location"	
•	task.	
	Effect:	
	NC program execution is inhibited or aborted,	
	the axis is brought to a standstill via the	
	deceleration ramp.	

Faults and Alarms 10.99

Number / Alarm	Cause	Counter-measure
A220	The decoded NC block contains several	Correct the NC block.
	mutually exclusive G functions from the zero	
Multiple zero offset	offset group (G53 to G59).	
selection not allowed		
	Example:	
	N1 G54 G58	
	The NC program number and NC block	
	The NC program number and NC block number in which the NC block decoder	
	detected the error can be read out with the	•
	"output actual values - decoder error location"	
	task.	A (2)
	Effect:	
	NC program execution is inhibited or aborted,	
	the axis is brought to a standstill via the	
	deceleration ramp.	
A221	The decoded NC block contains several	Correct the NC block.
Multiple tool offeet	mutually exclusive G functions from the tool	
Multiple tool offset selection not allowed	offset selection group (G43/G44).	
Selection not allowed	Example:	
	N1 G43 G44 D2	
	0.0022	
	The NC program number and NC block	\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
	number in which the NC block decoder	
	detected the error can be read out with the	
	"output actual values - decoder error location"	
	task.	
	Effects	
	Effect:	
	NC program execution is inhibited or aborted, the axis is brought to a standstill via the	
	deceleration ramp.	
A223	The decoded NC block contains a subprogram	Correct the NC block.
7.220	call, however the NC program which was	Correct tile 110 block.
Subprogram number	called does not exist in the memory of the	
does not exist	technology.	
	Effect:	
	NC program execution is inhibited or aborted,	
	the axis is brought to a standstill via the	
A224	deceleration ramp.	Correct the NC program
744	The permissible nesting depth of subprograms was exceeded. Recursive calling of	Correct the NC program.
Subprogram nesting	subprograms.	The permissible nesting depth for
depth not allowed		subprograms is 2 subprogram levels.
	The NC program number and NC block	, 3
	number in which the NC block decoder	
	detected the error can be read out with the	
	"output actual values - decoder error location"	
	task.	
	Title at	
. (Effect:	
	NC program execution is inhibited or aborted, the axis is brought to a standstill via the	
	deceleration ramp.	
	Lucociciation famp.	

10.99 Faults and Alarms

Number / Alarm	Cause	Counter-measure
A225	The decoded NC block contains simultaneous	Correct the NC block.
Otatus of av W. 1	selection and deselection of collision	
Status of collision	monitoring (G96/G97).	
monitoring select. not allowed	Example: N1 G96 G97 X100	
	The NC program number and NC block	
	number in which the NC block decoder	
	detected the error can be read out with the	◆
	"output actual values - decoder error location" task.	
	task.	. 60
	Effect:	
	NC program execution is inhibited or aborted,	
	the axis is brought to a standstill via the	
A227	deceleration ramp. The look-ahead function of the decoder has	Correct the NC program.
AZZI	detected that the negative software limit switch	Check the machine data.
Negative overtravel	will be crossed. See also error message	
violated	"A195: Negative overtravel reached".	
	The NC program number and NC block	
	The NC program number and NC block number in which the NC block decoder	
	detected the error can be read out with the	
	"output actual values - decoder error location"	
	task.	
	F#oot:	
	Effect: NC program execution is inhibited or aborted,	
	the axis is brought to a standstill via the	
	deceleration ramp.	
A228	The look-ahead function of the decoder has	Correct the NC program.
Positive overtravel	detected that the positive software limit switch will be crossed. See also error message	Check the machine data.
violated	"A196: Positive overtravel reached".	
110.0.00		
	The NC program number and NC block	
	number in which the NC block decoder	
	detected the error can be read out with the "output actual values - decoder error location"	
	task.	
	Effect:	
	NC program execution is inhibited or aborted,	
	the axis is brought to a standstill via the deceleration ramp.	
A241	The table assignment has been changed from	Load the table again.
	1 table to 2 tables or vice-versa.	
Table assignment	Fiforti	Note:
changed	Effect: NC tables cannot be processed.	A table can only be loaded again if it is not selected. The warning is cleared automatically
	tables callifor be processed.	when the table has been successfully loaded.
A242	Table 1 was not loaded correctly or has been	Load table 1 again.
	reset.	
Table 1 invalid	Ked	Note:
	Effect: Table 1 cannot be processed.	Table 1 can only be loaded again if it is not selected. The warning is cleared automatically
	Table I calliot be processed.	when table 1 has been successfully loaded.
A243	Table 2 was not loaded correctly or has been	Load table 2 again.
	reset.	
Table 2 invalid	Effect	Note:
	Effect: Table 2 cannot be processed.	Table 2 can only be loaded again if it is not selected. The warning is cleared automatically
*	Table 2 calliot be processed.	when table 2 has been successfully loaded.
	I.	,

Faults and Alarms 10.99

Number / Alarm	Cause	Counter-measure
A244	Travel table 3 has not been correctly adopted	Adopt travel table 3 again.
	or has been reset.	
Travel table 3 not valid		Note:
	Consequence:	Travel table 3 can only be newly adopted if it is
	Travel table 3 cannot be processed.	not selected. When travel table 3 has been
		successfully adopted, the alarm message is
		automatically canceled.
A245	Travel table 4 has not been correctly adopted	Adopt travel table 4 again.
Township his America Cal	or has been reset.	Neter
Travel table 4 not valid	0	Note:
	Consequence:	Travel table 4 can only be newly adopted if it is
	Travel table 4 cannot be processed.	not selected. When travel table 4 has been
		successfully adopted, the alarm message is
A246	Travel table 5 has not been correctly adopted	automatically canceled. Adopt travel table 5 again.
A240	or has been reset.	Adopt traver table 5 again.
Travel table 5 not valid	or has been reset.	Note:
Traver table 3 flot valid	Consequence:	Travel table 5 can only be newly adopted if it is
	Travel table 5 cannot be processed.	not selected. When travel table 5 has been
	Traver table 3 carrier be processed.	successfully adopted, the alarm message is
		automatically canceled.
A247	Travel table 6 has not been correctly adopted	Adopt travel table 6 again.
	or has been reset.	· · · · · · · · · · · · · · · · · · ·
Travel table 6 not valid		Note:
	Consequence:	Travel table 6 can only be newly adopted if it is
	Travel table 6 cannot be processed.	not selected. When travel table 6 has been
		successfully adopted, the alarm message is
		automatically canceled.
A248	Travel table 7 has not been correctly adopted	Adopt travel table 7 again.
	or has been reset.	
Travel table 7 not valid		Note:
	Consequence:	Travel table 7 can only be newly adopted if it is
	Travel table 7 cannot be processed.	not selected. When travel table 7 has been
		successfully adopted, the alarm message is
		automatically canceled.
A249	Travel table 8 has not been correctly adopted	Adopt travel table 8 again.
Travel table 8 not valid	or has been reset.	Notes
rraver table 8 not Valid	Conneguence	Note:
	Consequence:	Travel table 8 can only be newly adopted if it is not selected. When travel table 8 has been
	Travel table 8 cannot be processed.	
		successfully adopted, the alarm message is automatically canceled.
	• • • • • • • • • • • • • • • • • • •	automatically canceled.

Table 12-2 Alarm numbers, causes and their counter-measures

10.99 Faults and Alarms

12.3 Fatal errors (FF)

Fatal errors are serious hardware or software errors which no longer permit normal operation of the unit. They only appear on the PMU in the form "FF<No>". The software is re-booted by actuating any key on the PMU.

Number / Fault	Cause	Counter-measure
FF01	A time slot overflow which cannot be remedied	- Reduce pulse frequency (P340)
Time a plat accomplant	has been detected in the high-priority time	- Replace CU
Time slot overflow	slots.	
FF03	Serious faults have occurred while making access to external optional boards (CB, TB,	- Replace the CU
Access fault	SCB, TSY).	- Replace the LBA
Optional board		- Replace the optional board
FF04	A fault has occurred during the test of the RAM.	Replace CU
RAM		
FF05	A fault has occurred during the test of the EPROM.	Replace CU
EPROM fault		_ (//F
FF06	Stack has overflowed	For VC: Increase sampling time (P357) For MC: Reduce pulse frequency (P340)
Stack overflow		- Replace the CU
FF10		
Compact PLUS only		
FF13	A version conflict between the firmware and	- Replace firmware
	the hardware has occurred.	- Replace CU
Wrong firmware version	4)	
FF14	Unexpected fatal error	Replace the board
FF processing	(During processing of the fatal errors, a fault number has occurred which is unknown to date).	
FF15	Stack overflow (C-Compiler Stack)	Replace the board
CSTACK_OVERFLOW	•	

Table 12-3 Fatal errors

MAN Westical Still Still

10.98 Environmental Friendliness

13 Environmental Friendliness

Environmental aspects during the development

The number of components has been significantly reduced over earlier converter series by the use of highly integrated components and the modular design of the complete series. Thus, the energy requirement during production has been reduced.

Special significance was placed on the reduction of the volume, weight and variety of metal and plastic components.

Plastic components used

PC: Front cover

ABS: Fan mesh, PMU support board, logo

PP: Hinges, insulating board, handle, bus retrofit PA6: Insulating foils, terminal housing, support

Halogen-containing flame retardants were, for all essential components, replaced by environmentally-friendly flame retardants. Environmental compatibility was an important criterium when selecting the supplied components.

Environmental aspects during production

Purchased components are generally supplied in recyclable packaging materials (board).

Surface finishes and coatings were eliminated with the exception of the galvanized sheet steel side panels.

ASIC devices and SMD devices were used on the boards.

The production is emission-free.

Environmental aspects for disposal

The unit can be broken down into recyclable mechanical components as a result of easily releasable screw and snap connections.

The plastic components are to DIN 54840 and have a recycling symbol.

Units can be disposed of through certified disposal companies. Addresses are available from your local Siemens partner.

MAN Westical Still Still

10.98 Certificates

14 Certificates

SIEMENS

Automation and Drives

Confirmation

Erlangen, 01.05.1998

This confirms that

Equipment

AC drive converter

Type

SIMOVERT MASTERDRIVES

Order No.

6SE70...

is manufactured in conformance with DIN VDE 0558, Part 2 and EN 60204, Part 6.2 (

□ DIN VDE 0113, Part 6.2).

This equipment fulfills the protection requirements against electric shock according to DIN VDE 0106 Part 100 when the following safety rules are observed:

- Service work in operation is only permissible at the electronics box
- The converter must be switched into a no-voltage condition and isolated from the supply when replacing any part/component
- All panels must be closed during operation.

Thus, this equipment conforms to the appropriate regulations in Germany according to VBG 4 §2 (2) (VBG is a German regulatory body for safety-related issues).

The local operating regulations (e.g. EN 50110-1, EN 50110-2) must be observed when operating the equipment.

A&D DS A P1

Mickal

Certificates 10.98

SIEMENS

Automation and Drives

Test certificate

Erlangen, 24.08.1998

Equipment

Type

Order No.

AC drive converter SIMOVERT MASTERDRIVES 6SE70...

The 100% inspection was performed according to test instructions

475 100.9000.00 QP size A - D 476 100.9000.00 QP size E - G 476 200.9000.00 QP size J

Test scope:

- I. Insulation test
- II. Function test acc. to EN 50178
- III. RUN-IN
- IV. Function test acc. to EN 50178

- Refer to EN 50178, Part 9.4.5.2 and UL508/CSA 22.2-14.M 91, Part 6.8
- Initialization and start-up
- Customer terminals
- Power section inspection
- Inspection of protection and monitoring devices
- Continuous test > 5 hours ambient temperature 55 °C
- see II. Function test

The equipment complied with the test requirements. The test results are documented within the test data base

1) For complete type, serial number and technical data please see rating plate.

A&D DS A PE D P

Schlögel

Automation & Drives 10.98 Certificates

SIEMENS

Factory certificate *

regarding electromagnetic compatability

4SE.475 000 0001.00 WB EMV

Manufacturer: Siemens Aktiengesellschaft

Automation & Drives Group

Business Division Variable-speed drives

Sub-Division AC-Drive systems

Address: P.O. Box 3269

D-91050 Erlangen

Product name: SIMOVERT

Type 6SE70 Compact drive converters AC-AC and DC-AC

When correctly used, the designated product fulfills all the requirements of Directive 89/336/EEC regarding electromagnetic compatibility.

We confirm the conformance of the above designated product with the Standards:

EN 61800-3 10-1996

EN 61000-4-2 (old IEC 801-2)

EN 61000-4-4 (old IEC 801-4)

EN 61000-4-5 (old IEC 801-5)

IEC 1000-4-3 (old IEC 801-3)

EN 55011 (DIN VDE 0875 Part 11)

Note:

These instructions relating to EMC-correct installation, correct operation, connecting-up conditions and associated instructions in the product documentation supplied must be observed.

Erlangen, 01.05.1998

H. Mickal

A&D DS A P1

&Drives

*) acc. to EN 10204 (DIN 50049)

This declaration does not guarantee any features.

A&S DS 4102x

Copyright (©) SIEMENS AG 1997 All rights reserved

Page 1 of 1

Bisher sind folgende Ausgaben erschienen:

Ausgabe	Interne Sachnummer			
AA	475 944 4170 76 J AA-74			
AB	475 944 4170 76 J AB-74			
AC	475 944 4170 76 J AC-74			
AD	A5E00394444			

Ausgabe AD besteht aus folgenden Kapiteln:

Kapitel		Änderungen	Seitenzahl	Ausgabedatum
1	Definitionen und Warnungen	überarbeitete Ausgabe	4	10.98
2	Beschreibung	überarbeitete Ausgabe	1	10.98
3	Erstinbetriebsetzung	überarbeitete Ausgabe	2	10.98
4	Transportieren, Lagern, Auspacken	überarbeitete Ausgabe	1	10.98
5	Montage	überarbeitete Ausgabe	5	10.98
6	EMV-gerechter Aufbau	überarbeitete Ausgabe	2	10.98
7	Anschließen	überarbeitete Ausgabe	11	10.99
8	Parametrierung	überarbeitete Ausgabe	30	10.99
9	Wartung	überarbeitete Ausgabe	5	10.98
10	Formieren	überarbeitete Ausgabe	2	10.98
11	Technische Daten	überarbeitete Ausgabe	6	10.99
12	Störungen und Warnungen	überarbeitete Ausgabe	37	10.99
13	Umweltverträglichkeit	überarbeitete Ausgabe	1	10.98
14	Bescheinigungen	überarbeitete Ausgabe	3	10.98

The following editions have been published so far:

Edition	Internal Item Number
AA	475 944 4170 76 J AA-74
AB	475 944 4170 76 J AB-74
AC	475 944 4170 76 J AC-74
AD A5E00394444	

Version AD consists of the following chapters:

Chapter		Changes	Pages	Version date
1	Definitions and Warnings	reviewed edition	4	10.98
2	Description	reviewed edition	1	10.98
3	First Start-up	reviewed edition	2	10.98
4	Transport, Storage, Unpacking	reviewed edition	1	10.98
5	Installation	reviewed edition	5	10.98
6	Installation in Conformance with EMC Regulations	reviewed edition	2	10.98
7	Connecting-up	reviewed edition	11	10.99
8	Parameterization	reviewed edition	30	10.99
9	Maintenance	reviewed edition	5	10.98
10	Forming	reviewed edition	2	10.98
11	Technical Data	reviewed edition	6	10.99
12	Faults and Warnings	reviewed edition	35	10.99
13	Environmental Friendliness	reviewed edition	1	10.98
14	Certificates	reviewed edition	3	10.98

Automation and Drives Motion Control Systems
Postfach 3180, D-91050 Erlangen

Subject to change