


SCALE X 10 = CURRENT IN AMPERES



Type CLS Motor Starter Current Limiting Fuses
Let-Thru Current Curves, 2.54 to 5.08 kV

● Changed since previous issue.
Westinghouse Electric Corporation
Distribution and Control Business Unit
Greentree, PA 15220
Printed in USA

Supersedes Curve No. 9
dated January, 1986

July, 1986

9

Reference Data			
Curve:	1 and 2	3	4 Thru 14
Ref. Curve No.	667002	667008	639315
Date:	6-16-78	9-13-79	2-22-71